

SUMMARY OF OPERATIONS

DESTRUCTION OF TWO WATER-SUPPLY WELLS BOEING REALTY CORPORATION C-6 FACILITY LOS ANGELES, CALIFORNIA

Prepared for:

Integrated Environmental Services, Inc.

Prepared by:

Richard C. Slade & Associates Consulting Groundwater Geologists North Hollywood, California

RCS Job No. S9808

September 1998




INTRODUCTION

This Summary of Operations report has been prepared to document procedures and methods used in the destruction of two former water-supply wells at the Boeing Realty Corporation (BRC) C-6 Facility. This facility, as seen on Figure 1 - Site Location Map - is located on the southwest corner of the intersection of 190th Street and Normandie Avenue, in the City of Los Angeles, California. Figure 2 -Well Location Map- illustrates the approximate location of the two water-supply wells at the facility.


Beylik Drilling Company (Beylik) of La Habra, California was the contractor that performed the actual well destruction work. Richard C. Slade & Associates, Consulting Groundwater Geologists (RCS) prepared the guidelines for destruction of the wells, and was present to monitor and observe the well destruction work at certain tasks, as herein described. RCS personnel also maintained liaison with Beylik personnel and Integrated Environmental Services, Inc. (IES) personnel (primarily Mr. Chris Stoker) during each work task to provide inprogress information on the well destruction work. The California Regional Water Quality Control Board (CRWQCB) was also apprised by IES of events during destruction of the wells.


All destruction procedures were performed based on an RCS Workplan June 1998 and were conducted in accordance with current California Department of Water Resources (DWR) well standards as outlined in DWR Bulletin 74-81 and its supplement DWR Bulletin 74-90. Prior to destruction, a Los Angeles County Department of Health Services (LACDHS) Well Destruction Permit was obtained by Beylik.

During work on the well destruction project, addenda to the original Workplan and other correspondence were submitted by RCS to IES personnel, based on conversations with IES personnel and based on RCS observations. Appendix I includes the addenda and correspondence submitted to IES personnel that outline the minor changes to the original Workplan and also provides the RCS final recommendations regarding destruction operations of the two wells.




Base Map: USGS 7.5-minute Torrance Topographic Quadrangle





Base Map Modified from Integrated Environmental Services, Inc.





BACKGROUND INFORMATION

Available information reveals that initially three water-supply wells, Nos. 1 through 3, were constructed at the subject site in the mid-1940's. According to Los Angeles County Department of Public Works, Flood Control District (LACFCD) data, the three wells are/were designated as follows:

Owner Well Number	LACFCD Number	U.S. Geological Survey Number	California Department of Water Resources Number
1	794A	T4S/R14W-1H1	T4S/R14W-1F1
2	794B	T4S/R14W-1H2	T4S/R14W-1F2
3	794C	T4S/R14W-1H3	T4S/R14W-1F3

Well No. 1 reportedly no longer exists at the site, and there are no records to document when and how Well No. 1 was destroyed. The remaining two wells (Nos. 2 and 3) had not been used in many years but were still equipped with deep well turbine pumps.

Original driller's logs reveal that Well Nos. 2 and 3 were drilled for the Aluminum Corporation of America (ALCOA) between July and September 1942. The wells were drilled by the Roscoe Moss Company, most likely by the cable tool drilling method. The following table shows the construction parameters of each well, as documented in the original driller's logs.

Well Number	Depth (ft, bgs)	Diameter of Steel Casing (inches)	Perforation Intervals (ft, bgs)
2	600	14	477-506 525-530 535-540
3	600	14	427-433 478-516 538-550



The perforations in each well were generally 5/16 inches in width and were 1-3/14 inches in length. A copy of the original driller's log for both wells is included in Appendix 2.

WELL DESTRUCTION PROCEDURES

The following work items were conducted during the destruction of each well.

1. Pump Removal

The existing well pump components (the turbine drive head, pump column, and pump bowls) in each well were removed by Beylik. Pump removal was performed utilizing an overhead lift to vertically extract the pump components from each well. During removal, the pump column in each well was torch-cut in lengths of 10 ft as the pump was removed from each well. After removal from each well, all pump components were left onsite for disposal by BRC; these components, due to their age, had no salvage value.

The pump from Well No. 3 was removed on July 6 and 7, 1998. Fourteen sections of 10-inch-OD, 10-ft-long pump column, one section of 4-foot-long column, and one section of 6-foot-long column were removed from this well. The underlying pump bowl assembly was approximately 11½ ft long, consisting of 15 stages (each stage was approximately 8 inches long). A 10-foot-long suction pipe with a 3-foot-long strainer were below the bottom of the bowls, and these lengths brought the original total depth of the pump intake in the well to approximately 174 feet.

The pump from Well No. 2 was removed on July 22 and 23, 1998. Seven sections of 7-inch-OD, 20-ft-long pump column were removed from the well. The pump bowl assembly was approximately 12 ft long, consisting of 16 stages (each stage being approximately 8 inches long). A 5-foot-long tail pipe brought the original total depth of the pump intake in the well to approximately 157 feet.

2. Flocculation of Water in Casing

To prepare the water in the well casing for video surveying in each well, a flocculent was used to remove and/or settle suspended material in the fluid column in the well. The



flocculent used consisted of a lime-water mixture prepared at the surface. This inert mixture was poured directly down each well and thereafter the well was allowed to set prior to performing additional work. Following flocculent application, Well No. 3 was allowed to set for a period of 48 hours and Well No. 2 was allowed to set for a 24-hour time period.

3. Water Well Video Survey

Following removal of the pump and flocculation of the fluid column, a video log survey was conducted in each well. This video survey used a combination vertical/sidescan color camera to examine and document, on VHS tape, the field of view of the blank and perforated sections of casing during the vertical descent of the camera into each well. The sidescan option was used to examine, at appropriate points and where necessary, the physical condition of the casing and/or perforations.

The video survey in Well No. 3 was performed on July 9, 1998 by Water Well Developers, Inc. of Anaheim, California. The video survey in Well No. 2 was performed on July 23, 1998 by the same company. An RCS geologist was present during each survey to record the casing conditions in each well as observed on the video log. A record of those observations is included in the Appendix.

Observation of the video survey for Well No. 3 revealed that the uppermost perforation intervals differed slightly than those documented in the original driller's log. For instance, top of perforations was observed at a depth of 423 ft bgs. However, the driller's log documents the top of perforations at a depth of 427 ft bgs. At a depth of 483 ft sediment fill was encountered. Thus, the intervals of the remaining perforations between 483 ft and 550 ft bgs could not be confirmed. Because the original depth of the well is 596 ft, the video log shows that approximately 113 ft of sediment fill occurred in the well at the time of the video survey.

Observation of the video survey for Well No. 2 revealed that perforations were generally observed where they are documented to occur on the driller's log of the well. However, due to poor visibility the perforations were difficult to see. Sediment fill occurred at a depth of approximately 544 ft bgs. The driller's log shows that the bottom of the well originally occurred at a depth of 596 ft bgs. Thus, based on the video log approximately 52 ft of sediment fill occurred at the time of the video survey.



4. <u>Bailing and Sampling of Sediment Fill</u>

Following the video survey, each well was found to contain sediment fill in the bottom of the casing. The thickness of this sediment fill was 113 ft in Well No. 3 and 52 ft in Well No. 2. This sediment fill in each well accumulated over time due to pumpage of fine grained formation sand. Such sand pumpage was common in old cable-tool drilled wells in the region due to the irregular size and slope of typical casing perforations and to the fine grained nature of several aquifers in the region.

A limited amount of the sediment fill that had accumulated in the bottom of each well was removed by bailing. This bailing was performed for the purpose of collecting sediment samples from the bottom of each well, which then could be transported to a laboratory for analysis. The objective of the sampling and analysis was to determine if the sediment fill, comprised of native fine-grained materials, could be left in place in each well.

Bailing consisted of lowering a 10-inch-diameter metal bailer equipped with a single bottom end flap to the bottom of each well to capture and lift the collected sample to the surface. After the bailer has been lowered to the bottom of each well, the bailer was repeatedly lowered and raised in short increments to move sediment up into the bailer. The bailer was then brought to the surface and the contents placed into a 290-gallon trough.

Bailing of Well No. 3 was conducted on July 13, 1998 and resulted in the removal of approximately 7 ft of sediment, bringing the total depth of the well to approximately 490 ft. Well No. 2 was bailed on July 24, 1998; approximately, 22 feet of sediment was removed from this well, resulting in a total well depth of approximately 566 feet.

The sediment bailed from the bottom of each well generally consisted of a medium to dark gray, fine- to coarse-grained sand containing minor accessory shell material. This bailed sediment was determined by RCS personnel to be native material.

The sediment samples were submitted to Del Mar Analytical Laboratory in Van Nuys, California, and analyzed for volatile organic compounds (VOCs, by EPA Method 8260), semi-volatile organic compounds (SVOCs, by EPA Method 8270), metals (including Chromium VI), and pH. Copies of the results of laboratory analyses for the sediment samples from each well are included in Appendix 4.



The results of laboratory analysis revealed that sediment from Well No. 3 indicated the presence of only one VOC, chloroform; its reported concentration was 0.0036 milligrams per kilogram (mg/Kg). All other VOCs or SVOCs were reported to be detected at concentrations below their respective laboratory limits in the sediment sample.

However, the Total Threshold Limit Concentration (TTLC) values for three metals, total chromium (Cr), copper (Cu), and nickel (Ni), were detected in the sediment sample from Well No. 3 in concentrations approximately 10 times above their Soluble Threshold Limit Concentration (STLC) values. As a result, those three metals were further analyzed for STLC extraction. The following table summarizes those results:

Metal	TTLC Sample Result (mg/Kg)	TTLC Maximum Limit (mg/Kg)	STLC Sample Result (mg/Kg)	STLC Maximum Limit (mg/Kg)
Cr (total)	97	2500	<0.10	5
Cu	300	2500	1.0	25
Ni	190	2000	0.29	20

The results of that test showed that the detected STLC values for each tested metal were reported to be below their respective STLC values. In addition, chromium VI was reported to be the at laboratory detection limit for that metal.

The metals were not leachable, as shown by the STLC testing. It is suspected that the Cr, Cu, and Ni detected in the original sediment sample may have been due to minor amounts of scale present in the sample (refer to and compare the sample analysis of sediment from Well No. 2, which contained no scale, with well No. 3 which contained scale; see below). This scale may have originated from either the well and/or pump column and was likely knocked off during removal of the pump or during bailing of the sediments. Therefore, the sediment samples from Well No. 3 are considered to be native material, and it was recommended that the



remaining sediment be left in place in the bottom of this well. Approximately 106 ft of sediment fill remained in Well No. 3 prior to final well destruction.

The results of laboratory analysis revealed that bottom sediment in Well No. 2 showed all reported VOC and SVOC concentrations to be below their laboratory detection limits. In addition, all metal concentration values were below their respective TTLC and STLC values. Further, chromium VI was reportedly not detected in the sediment sample.

Thus, the sediment samples from Well No. 2 are considered to be native materials, and it was recommended that the remaining sediment be left in place in the bottom of the well. Approximately 30 ft of sediment fill remained in the well prior to final well destruction.

5. Perforation of Well Casing

Because the depth to uppermost, existing perforations in each well begins at relatively great depths (477 ft and 427 ft in Well Nos. 2 and 3, respectively, based upon driller's logs), and because the video log surveys showed the existing perforations to be at least partially plugged, it was recommended that additional perforations be added to shallower portions of the casing to enable the eventual well grouting to enter additional native materials outside the existing casing. Hence, the upper portion of each casing was perforated with a down-well mechanical perforator tool. Additional perforations were placed within blank casing at depths ranging from 200 ft to 400 ft bgs, in each well as described below. A Mills knife, mechanical perforator was used to perforate the casing. Perforations consisted of 8 cuts per row, with each row being approximately one foot apart.

Well No. 3 was perforated on August 12, 1998 from 450 to 470 ft. Following this, cement grout was installed from 490 ft up to 385 ft bgs (as described in the following section). Then, on August 14, 1998, additional casing perforations were cut from 380 to 385 ft, 310 to 340 ft, 250 to 270 ft, and 200 to 220 ft in this well.

Well No. 2 was perforated on August 19, 1998 from 430 to 460 ft, and then cement grout was installed from 566 ft up to 346 ft bgs (as described in the following section). Then on August 21, 1998, well casing perforations were cut from 310 to 330 ft, 260 to 280 ft, and 210 to 230 ft in this well. Thereafter, cement grout was installed as described below.



6. Well Grouting and Installation of Mushroom Cap

The cement grout for well destruction was 10.3-sack mix sand-cement grout. Cement used for the seal was a standard brand Portland cement conforming to ASTM C150, Type II. There was not more than two parts by weight of sand to one part by weight of cement. The water-cement ratio was about 7 gallons per sack of cement (94 pounds).

The cement grout was injected into the well casing from the bottom upward by means of a temporary grout tremie pipe. Cement grout materials were placed by a positive displacement method using pumping. Grout was placed in each well between perforating the upper and lower zones (as discussed in No. 5 above), resulting in two separate lifts or grout placement.

The first lift in Well No. 3 was placed on August 13, 1998 and consisted of placing 3½ cubic yards (yd³) of cement grout. This amount of grout filled the well from 490 ft bgs up to a depth of approximately 385 ft (105 lineal ft of cement grout). After perforating the upper casing zones (i.e., above 385 ft bgs), perforations were placed in the intervals as noted in No. 5 above after which additional grouting was performed. The second lift of cement grout was installed on August 17. Approximately 10 yd³ of cement grout were used to fill the casing for this lift from 385 ft up to a depth of 55 ft bgs (330 lineal ft of cement grout). On August 20, 1998, the area around the top of the well casing was excavated using a backhoe. The exposed casing was cut off at a depth of approximately 5 ft bgs, and the cement mushroom cap was installed. Approximately 6 yd³ of cement grout were used in the installation of the mushroom cap in Well No. 3. Copies of the cement delivery tickets are included in Appendix 5. After the mushroom cap set, the excavation was backfilled with native earth materials up to the level of adjoining grade.

The first lift in Well No. 2 was placed on August 20, 1998 and consisted of placing 7 yd³ of cement grout. This amount of grout filled the well from 566 ft bgs up to a depth of approximately 346 ft (220 lineal ft of cement grout). After grouting, perforations were placed in selected casing intervals above 346 ft bgs, (see depths in previous section), after which additional grouting was performed.

On August 27, 1998, the remaining 4 ft of well was cemented in by Beylik personnel. As a result, the second lift of cement grout in Well No. 2 was installed on August 24, 1998. Approximately 16 yd³ of cement grout were used to fill the casing from 346 ft up to a depth of 4



ft bgs (342 lineal ft of cement grout). Copies of the cement delivery tickets are included in Appendix 5.

Just prior to conducting the final grouting of the remaining portion of Well No. 2, Mr. Chris Stoker of IES obtained approval from the CRWQCB to grout up the entire well and to perform the installation of the mushroom cap at a later date, during demolition of nearby structures at the site.

Closure

The following paragraphs summarize destruction operations at Well Nos. 2 and 3.

- A. The pump head, all pump column, and pump bowls were removed from each well. A total of 174 ft of pump column and bowls were removed from Well No. 3 and a total of 157 ft were removed from Well No. 2.
- B. An inert lime-water solution was added to each well to improve water clarity for a video survey in each well.
- C. Observation of the video surveys revealed a static water level in each well at 106 ft bgs. Sediment fill was encountered in Well No. 3 at a depth of approximately 483 ft. Sediment fill was encountered in Well No. 3 at a depth of approximately 544 ft bgs. Generally the well casing in each well was encrusted with scale/biofilm and perforations were generally partially clogged to clogged.
- Laboratory analyses of a sample of sediment fill near the bottom of each well indicated that the sediment fill is considered to be native earth materials. As a result the remaining fill after bailing (30 ft in Well No. 2 and 106 ft in Well No. 3) was left in the bottom of each well during the well destruction process.
- E. Due to the clogged to partially clogged perforations in each well, a casing perforator tool was used to place additional perforations in each well. Initially, additional perforations were placed in the 430-foot to 460-foot range in Well No. 2 and in the 450-foot to 470-foot range in Well No. 3.
- F. Following the initial set of additional perforations, an initial lift of cement grout was installed in each well. In Well No. 3 cement grout was installed from 566 ft to 346 ft and used a total of 7 yd³. In Well No. 3, 3½ yd³ of cement grout was installed from 490 ft up to 385 ft bgs.
- G. After the initial lift of grouting in each well, additional perforations were installed in the well casing. In Well No. 2, additional perforations were placed



in the 210- to 230-foot, 260- to 280-foot, and 310- to 330-foot interval. In Well No. 3, additional perforations were placed in the 200- to 220-foot, 250- to 270-foot, 310- to 340-foot, and 380- to 385-foot intervals.

H. A second lift of grout was then placed after the additional perforations had been cut into the casing of each well. In Well No. 2, the remaining well casing was grouted from 346 ft up to ground surface. Approximately 16 yd³ of cement were used to grout Well No. 2 from 346 ft up to 4 ft bgs. The upper 4 ft in Well No. 2 were cemented-in manually. Cut-off of the upper 4 ft of casing and installation of the final mushroom cap in Well No. 2 are to be completed at a later time, during demolition of other nearby structures at the site.

In Well No. 3, approximately 16 yd³ of cement grout were used to fill the well casing from 385 ft to ground surface and to install the mushroom cap (following excavation of the well pad and cut-off of the casing to 5-feet bgs). After installation of this mushroom cap, the small excavation was backfilled, thereby completing the destruction of Well No. 3.

The above outlined procedures were conducted in accordance with DWR Bulletin 75-81 and 74-90 guidelines. As a result, complete destruction of the two wells has been achieved and request for project closure is hereby requested. The attachments and appendices complete this report.

Respectively submitted:

RICHARD C. SLADE & ASSOCIATE

Earl F. LaPensee

Certified Hydrogeologist No. 134

lighard C. Slade

Certified Engineering Geologist No. 929



APPENDIX 1 ADDENDA AND CORRESPONDENCE





July 24, 1998

Mr. Chris Stoker, Program Manager Integrated Environmental Services, Inc. 3990 Westerly Place, Suite 210 Newport Beach, California 92660

Job S9808

Re:

Video Log Results and Final Recommendations

For Destruction of Well No. 2

Boeing Realty Corporation C-6 Facility, Torrance, California

Dear Mr. Stoker:

Presented herein are the results of the video log survey of Well No. 2 and our final recommendations for the permanent destruction of this well.

Video Log Results

On Thursday, July 23, 1998 at 2:00 pm a video log survey of the subject well was performed by Mr. John MacDonald of Water Well Redevelopers, Inc. of Anaheim. Witnesses to the video log included Mr. Dean Garcia of Beylik Drilling Company, Ms. Joann Ornelas, yourself, and Earl LaPensee of Richard C. Slade & Associates. Mr. John Marasco, Site Superintendent for Boeing Realty Company, was present for a portion of the survey also. No one from the California Water Quality Control Board—Los Angeles Region was present during the video log survey. It should be noted that the conditions observed in Well No. 2 are similar in many respects to those observed during the video survey conducted in Well No. 3.

Unperforated (blank) well casing (14 inches in diameter) was observed from ground surface to a depth of approximately 477 ft below grade surface (bgs), the depth at which the uppermost perforations in the casing were first observed. The water surface in the well was observed to occur at 106 ft bgs, similar to that observed in Well No. 3. No oil was observed on this water surface. The clarity of the video survey was generally good from ground surface to an approximate depth of 215 ft bgs. However, below that depth the clarity decreased markedly due to the presence of floating material and cloudy water, even though the well was treated with lime solution and water was allowed to flow into the well for a minimum period of 26 hours. At particular depth intervals, the casing walls were barely observable although discernible.

At present, the potentiometric, non-pumping water level in the well occurs approximately 371 feet above the uppermost perforations. Because of this, the groundwater is under a strong positive hydraulic head. As stated for Well No. 3 this strong hydraulic head



would tend to preclude any shallower groundwater, if it occurs, from entering the casing during perforation of the 200-foot to 400-foot zone.

From about 215 ft bgs to the total depth of the well at 544 ft bgs, the clarity of the video log was poor. As a result, it was generally difficult to observe the perforations and/or the walls of the casing. However, it could be determined through the use of the side scan camera view that the uppermost perforations occur at 477 ft bgs and the bottom-most perforations occur at a depth of approximately 540 ft bgs. This confirms the general interval of perforations as noted in the drillers' log of the well. During vertical descent of the camera it was observed that there are no obvious holes, ruptures or collapses in the casing from ground surface to the present bottom of the well at 544 ft bgs. Because the bottom of the well is documented in the drillers' logs at a depth of 596 ft bgs then approximately 52 ft of sediment fill occurs in the well.

Where visible, existing perforations are of the hydraulic Mills knife variety. This further corroborates the cable too-drilled method of well construction. These perforations, where visible, appear to be plugged to a varying degree. Scale, also appears to occur to a varying degree on the inside of the blank casing. Such scaling and partial plugging of well casing is a typical phenomenon in older wells.

Final Recommendations for Well Destruction

Based on the video log survey, the following are our final recommendations for destruction of Well No. 2.

- Leave the existing 52-feet of sediment fill in the bottom of the well; this
 material represents fine- to coarse-grained sand and silt that entered through
 the large and irregularly-shaped Mills-knife cut perforations when the well
 was pumping. The amount of fill indicates that this well produced some
 amount of sand, although of lesser quantity than that apparently produced by
 Well No. 3.
- Place a 10.3-sack mix sand-cement grout, using a temporary grout tremie pipe, in the depth zone from 400 ft to the bottom of the well. Cement grout materials shall be placed by a positive displacement method by pumping through the tremie pipe.
- 3. Allow this cement to set for 24 hours.
- Utilize the hydraulic perforator tool to create additional new perforations in the casing as follows:
 - 380 to 400 ft
 - 310 to 340 ft
 - 250 to 270 ft
 - 200 to 220 ft

3



- 5. Place a similar sand-cement grout in the depth zone from 200 to 400 ft, using the same positive displacement pumping method.
- 6. Allow this cement to set for 24 hours.
- 7. Following setting of cement seal, the mushroom cap may be installed. Details concerning the cement type and the installation of the mushroom cap, etc. are provided in our Workplan dated June 1998.

Very truly yours,

RICHARD C. SLADE & ASSOCIATES

Richard C. Slade

Registered Professional Hydrogeologist American Institute of Hydrology No. 106



July 9, 1998

Mr. Chris Stoker, Program Manager Integrated Environmental Services, Inc. 3990 Westerly Place, Suite 210 Newport Beach, California 92660

Job S9808

Re:

Video Log Results and Final Recommendations

For Destruction of Well No. 3

Boeing Realty Corporation C-6 Facility, Torrance, California

Dear Mr. Stoker:

Presented herein are the results of the video log survey of Well No. 3 and our final recommendations for the permanent destruction of this well.

Video Log Results

This morning a video log survey of the subject well was performed by Mr. John MacDonald of Water Well Redevelopers, Inc. of Anaheim. Witnesses to the video log included Mr. Dean Garcia of Beylik Drilling Company, yourself and the undersigned. Mr. John Marasco, Site Superintendent for Boeing Realty Company, was present for a portion of the survey also. No one from the California Water Quality Control Board-Los Angeles Region was present during the survey.

Unperforated (blank) well casing (14 inches in diameter) was observed from ground surface to a depth of 423 ft, the depth at which the uppermost perfs in the casing were first observed. The present water surface in the well occurs at 106 ft. Virtually no oil was observed on this water surface. The clarity of the video survey was good from ground surface. Casing joints, where visible, were typically encountered at 4-ft intervals; this is typical for cable tool-drilled wells.

The water surface occurs approximately 317 feet above the uppermost perforations. Because of this, the groundwater is under a strong positive hydraulic head. This strong head would preclude any shallower groundwater, if it occurs, from entering the casing during perforation of the 200- to 400-ft zone. However, it is unlikely that groundwater would be present in that depth zone since the driller's log for the well reveals the lithology to consist predominantly of a "Blue Clay."

From about 426 ft (*i.e.*, just below the depth of the uppermost perforations at 423 ft) to about 445 ft, the clarity of the video log was poor, and it was difficult to observe the perforations and/or the walls of the casing. Hence, the length of the uppermost zone of casing perforations (on the driller's log it is from 427 to 433 ft) could not be determined. However, because this zone actually began at 423 ft, the bottom of this zone is likely at or near 429 ft. Below 445 ft, water clarity improved again.

The next set of perforations were observed to begin at a depth of 475 ft. Per the original driller's log, this set was reported to be from 478 to 516 ft. At a depth of 483 ft, the camera encountered sediment fill; this depth represents the present bottom of the well. The original cased depth of the well was 596 ft. Hence, there is now approximately 113 ft of fine-grained sediment fill in the lower portion of the well.

As the camera descended into the well, side scan (horizontal) views of the camera were made to provide better observation of the perforations and/or walls of the casing. Such side scans were performed at 247 ft, 425 ft, 445 ft, 453 ft, 465 ft, and 477 ft. These observations coupled with observations of the well casing during vertical descent of the camera revealed there are no obvious holes, ruptures or collapses in the casing from ground surface to the present bottom of the well at 483 ft.

Where visible, existing perforations are of the hydraulic Mills knife variety, further corroborating the cable too-drilled method of well construction. These perforations appear to be plugged to a varying degree. Scale also appears to occur to a varying degree on the inside of the blank casing. Such scaling and partial plugging of well casing is a typical phenomenon in older wells.

Final Recommendations for Well Destruction

Based on the video log survey, the following are our final recommendations for destruction of Well No. 3.

- Leave the existing sediment fill in the bottom of the well; this material represents fine-grained sand and silt that entered through the large and irregularly-shaped Mills-knife cut perforations when the well was pumping. In essence, the well was a "sander."
- 2. Utilize a down-hole, hydraulic perforator tool to cut new perforations in the casing between the depths of 450 ft and 470 ft.
- 3. Place a 10.3-sack mix sand-cement grout, using a temporary grout tremie pipe, in the depth zone from 400 ft to 483 ft. Cement grout materials shall be placed by a positive displacement method by pumping through the tremie pipe.
- Allow this cement to set for 24 hours.



- 5. Utilize the hydraulic perforator tool to create additional new perforations in the casing as follows:
 - 380 to 400 ft
 - 310 to 340 ft
 - 250 to 270 ft
 - 200 to 220 ft
- Place a similar sand-cement grout in the depth zone from 200 to 400 ft, using the same positive displacement pumping method.
- 7. Allow this cement to set for 24 hours.
- Following setting of cement seal, the mushroom cap may be installed.
 Details concerning the cement type and the installation of the mushroom cap, etc. are provided in our Workplan dated June 1998.

Very truly yours,

RICHARD C. SLADE & ASSOCIATES

Richard C. Slade

Registered Professional Hydrogeologist American Institute of Hydrology No. 106



MEMORANDUM

DATE:

June 29, 1998

TO:

Chris Stoker, Integrated Environmental Services

FROM:

Richard C. Slade, Richard C. Slade & Associates

RE:

Change to Workplan

Well Casing Perforation.

Based on our conversation with you today, we understand that the California Regional Water Quality Control Board (RWQCB) has expressed concern over one aspect of our proposed method of destroying the two onsite Boeing Realty Corporation C-6 Facility water-supply wells. Specifically, the RWQCB is very concerned with the time lag between perforation of the casing above the screened zone in each well and the final sealing of each well with grout.

We note their concern and, as a result, recommend that the well sealing work be conducted as follows in each well:

- 1) Following bailing of sediment fill, seal the lower (known) perforations with grout up to a depth of approximately 400 ft in each well.
- 2) Allow the grout set for a minimum of 24-hours.
- 3) Perform down-hole perforation of the casing above the newly grouted zone in each well up to a depth of approximately 200 ft bgs.
- 4) Seal the remaining portion of the well up to a depth of approximately 50 ft bgs.

As a result of the change to the workplan conditions there likely will be no change in costs for the project. In addition, the contractor is scheduled to commence work at the site on or before July 6, 1998.

If you have any questions regarding this memorandum, please call me.



June 19, 1998

Mr. Chris Stoker Integrated Environmental Services 3990 Westerly Place, Suite 210 Newport Beach, California 92660

RE: Addendum to Workplan for Destruction of Two Water-Supply Wells at the Boeing Realty Corporation C-6 Facility, Los Angeles, California Workplan dated June 1998

Dear Mr. Stoker:

This letter amends the above titled workplan with regard to sampling and analysis of the bailed sediment from each water-supply well, outlined on Page 6 of the workplan, as follows:

- 1) Delete analysis for nitrate.
- 2) Add analyses for the sediment samples for volatile organic analysis (VOCs) utilizing Environmental Protection Agency (EPA) method 8260, semi-volatile organic compounds (SVOCs) utilizing EPA method 8270.
- 3) Add analysis for metals and pH.

If you have any questions regarding this letter, please call us.

Very truly yours,

Earl F. LaPensee



MEMORANDUM

DATE:

June 18, 1998

TO:

Chris Stoker, Integrated Environmental Services

FROM:

Richard C. Slade, Richard C. Slade & Associates

RE:

Reply to Regional Water Quality Control Board Letter (RWQCB) dated June 22, 1998, regarding the "Workplan for Destruction of Two Water-Supply Wells at the Boeing Realty Corporation C-6 Facility, Los Angeles,

California"

This memorandum outlines our reply to three items outlined by the RWQCB with regard to their review of the Destruction Workplan for the two wells at the Boeing Realty Corporation C-6 Facility in Los Angeles, California.

Item No. 1: Shallow groundwater contamination and perforation of well casing.

The RWQCB is concerned with the likelihood of contamination of the deeper aquifers contaminated by shallow groundwater during perforation of the upper portion of the well casing in each well. It is recognized that shallow groundwater has the potential for entering the wells during perforation. However, the time between perforation of the casing in each well and grouting of the well is on the order of a few days. Therefore the likelihood of contaminants being introduced into the deeper aquifers is low.

There are no known data on the potentiometric surface in each aquifer penetrated by the wells, due to the method of construction. However, the drillers' logs do reveal that water was first encountered at a depth of 67 ft, in Water Well No. 2, and 78 ft, in Water Well No. 3 (see Appendix 1 of Workplan). Regardless, current perforations in the two wells begin at depths of 540 ft in Water Well No. 2 and 550 ft in Water Well No. 3.

Item No. 2: Well sediment samples.

The samples will be analyzed for a complete suite of analyses, including SVOCs, VOCs, metals, and pH. Nitrate will be deleted from the specifications. These changes will be presented to you in an addendum to the workplan.



Memorandum to Chris Stoker, IES Boeing Realty Corporation Destruction Workplan for Two Water Wells

Item No. 3: Oil (free product) in well.

The RWQCB is concerned with the presence of oil in the well, if it is detected, and its impact on the aquifer, if any. Generally, the presence of oil is of no concern for the following reasons:

- 1. The oil, if encountered, would be lubricating oil for the deep well turbine pump and, hence, it would likely be free of all additives and other potentially toxic material.
- 2. The oil, if present, would be of a limited and relatively small volume.
- 3. The oil, if present, would only occur at the surface of the water, which is located in the blank well casing, considerably above the uppermost perforations in either well. Moreover, neither well has been reportedly pumped for at least 10 years or more.
- 4. Each well has perforations commencing at 540 ft to 550 ft (see Appendix 1 of Workplan). At originally reported pump rates of 810 gpm, for Water Well No 2, and 1375 gpm, for Well No. 3, drawdowns were 29 and 33 ft, respectively. This resulted in original specific capacities of approximately 28 gpm/ft ddn, for Well No. 2, and 42 gpm/ft ddn, for Water Well No. 3. Thus, original pumping levels were shallow, ranging from 112 ft to 116 ft and probably remained that way throughout the pumping history of the well. Such pumping levels are considerably above the uppermost perforations in either well.

The lubricating oil, if any, has never been below top of perforations and, consequently, has never come into direct contact with any aquifer in the well. As a result, it is not possible for the oil to have any impact on aquifers perforated by the wells. Thus, it is our recommendation that the oil not be sampled and analyzed.

Should you have any questions regarding this memorandum, please call us.



APPENDIX 2 ORIGINAL DRILLER'S LOGS OF WELLS

(DEFENSE PLANTS CORPORATION)

ROSCOE MOSS COMPANY 4380 WORTH STREET LOS AMOELES CAL

. rori					F46641" "26725"		America	
	cance,		fornia					<u> </u>
acs Loca	_				Sts.	, Los	Angela	ι.Ωα1
rted Wo	•	ust 3		<u> </u>		· · · · · · · · · · · · · · · · · · ·		
mpleted '	Work Se		er 17,	1942		····	-	
tal depth	600				of shoe_			
2005	t. ot	14	inch 10	. HERE:	dano espe	or used.	and we	n Well
							11 1	
***************************************						44		
						**		*
			- '`		••	, •• <u>.</u>		• ••
_	''	************	Hydra			**		' ".
•	referator t	neg					11	- ź /1
rforated_	540	tt.	to53		<u>_</u>	Но	les per 4	inches
"	<u> 530</u>		52	 ··	<u>8</u>	÷	** ************************************	• . •• "
**	506		"	<u> </u>			4. 4.	
"			**		•		* **	
·· · _			**			 •		
			11	······································	·			
٠٠	·····		:			<u> </u>		
"	·····		·· <u>:</u>			<u> </u>		4
		••	"				• • • • • • • • • • • • • • • • • • • •	
			**					
		••	••	·				•
,,			**			**********		- : -
••								
	H1 11111				·			•. "
~			**		·			. "
			**		***************************************	· ·		• "
** *	·······		**				Make diagram	ol man
"			5/16		•		Make diagram' teredan la sq showing dimen	
emoter o	f Porfors	tions			·····	inches		
ngth of	Porforatio	·	1-3			"		
oth at wi	hich water	was Aret		67				1
			64	***********	!			·
-	rel bofor:	berrors.		•				
enging la	rvel bofor: ivel after	-	· 47	<u> </u>	~~~~~~····	<u></u>		
unding le	vol after	perforati	· 47		i jood) mp	n• ••m; ∙- [······································	
unding le	vol after	perforati	83		e Janaj mp	no armi	2 	
unding le	vol after	perforati	83		r Josej mp	n•		
unding le	vol after	perforati	83		s Josel mp	na drini		
anding le	vol after	perforati	ing 83		r lovel wh	[na drini	12	
anding le	your observed a when ar	perforati	ing 83	te II meto	f Josef mp		3.5	
anding le	i when ir	perforati	ing 83	ge in wate			28	
nding louding	I when dr	perforation of the startes anding levents of the startes and t	of any changes of the state of	E3			25	
anding le	your observed when the grown state one per mi	perforation of the startes and	of any changed any changed when Topod when T	E3			DE .	
nding le nding le te below two level aw down of gallo	i when ir from sta- ma per mi one per mi	perforation of the start of the	ar Teet	E3				
anding le anding le te below the level aw down of gallo of gallo of down constion:	i when ir from sta- ma per mi one per mi	perforati avation c set started noting love note pum note pum note pum stich of "	of any changes of any	E3	artod B			
anding le anding le te below two level aw down of gallo of gallo ow down tmetton:	i when ir from sta- ma per mi one per mi	perforation of the property of	of any changes of any changes of any changes of the state	E3 est first at comple 29	arted g	ft		
unding le anding le te below ter level aw down of galle ow down cmetion: 0	i when ir from sta- ma per mi one per mi	perforation of the startes and the pum nuts pum still of the startes of the start	i Teet	83 est first at lest compile 29 y olay	artod B	ft		
unding le anding le te below atter level aw down of galle of galle of galle 65	i when ir from sta- ma per mi one per mi	perforation of startes of the starte	at Teet I Teet I Teet I Teet I Fant Sand Sand Fine	83 est first at comple 29 y clay y clay sand	arted wol S	it 		
nding le halow level lev	i when ir from sta- ma per mi one per mi	perforation of state of the sta	of any change of any change of any change of the control of the co	83 set first interpretation of complete complete 29 y olay y olay sand sand sand	arted star S	it 		
anding less anding less and less less less less less less less les	i when ir from sta- ma per mi one per mi	perforation of state of the sta	i Tost I Tost I Tost I Tost I Tost I Tost I Sand I Sand I Sand I Slue Blue	83 set first interpretation of complex 29 y clay y clay sand sand clay.	arted 6	to 10 atre	ake	
nding les anding les to below down of gallo of gallo 65 157 185 212	i when ir from sta- ma per mi one per mi	perforation of state of the first pure pure pure pure pure pure pure pure	i Tost I Tost	83 act first st. cost comple 29 y clay y clay sand and clay. sand	resoft and c	atre	ake	
nding le hading le he below down of gallo of gallo of gallo 157 157 1212 420 428	i when ir from sta- ma per mi one per mi	perforation of state pure pure pure pure pure pure pure pur	i Tost I Tost	83 set first st. set comple 29 y olay y olay sand sand clay. sand sand	resoft and c	to 10 atre	ake	
nding le hading le te below down of gallo of gal	i when ir from sta- ma per mi one per mi	perforation of state pum nuts	i Tost I Tost	83 set first st. set comple 29 y olay y olay sand sand clay. sand sand	resoft and c	atre	ake	
nding is to below down of gallo of gall	i when ir from sta- ma per mi one per mi	perforation of state pum nuts	i Tost I Tost	83 Set first st. Set comple 29 y clay y clay send sand clay sand sand clay	resoft and c	atre	ake	
nding le te below down of gallo of gallo of gallo 157 185 212 420 428 434 456 462	i when ir from sta- ma per mi one per mi	perforation of state pum nuts	of any changed when Trest gravel in Sand Fine Blue	83 est first int cost comple 29 y clay y olay sand sand clay sand sand clay sand	red do	atre	ake	
nding le te below down of gallo of gall	i when ir from sta- ma per mi one per mi	perforation of state pum nuts	of any changed wheal Trest ater gravel Sand Fine Blue Fine Blue Fine Blue Blue Fine Blue Fine Blue Fine Blue Fine	83 Set first at complex 29 y clay y olay sand sand clay sand sand clay	red decided and control and co	atre	ake	
anding le te below down of gallo of gal	i when ir from sta- ma per mi one per mi	perforation of started pure store started pure sta	of any changer of any	83 Set first art out comple 29 y olay y olay sand clay sand clay sand clay sand clay sand clay sand	red do	atre	ake.	
anding less anding less and le	i when ir from sta- ma per mi one per mi	perforation of the pure of the	of any changed wheal Trest gravel of Band Fine Blue Blue Blue Blue Blue Blue Blue Blu	83 Set first at complex 29 y clay y olay sand sand clay sand clay sand clay and cl	-soft and c and c and c	atre	ake.	
miding lo to below love love love love love love love love	i when ir from sta- ma per mi one per mi	perforation of the state of the	of any changed when Trest gravel and Sand Fine Blue Fine Blue Blue Blue Blue Blue Blue Blue Blu	83 Set first int Cost comple 29 y clay send sand clay sand clay sand clay and clay and clay and clay	r-soft and c to 3/ and c and c gravel gravel	atre	ake.	
mating is to below aw down of galle of	i when ir from sta- ma per mi one per mi	perforation of white purpose of the perforation of	of any change of	83 Set first int Cost comple 29 y olay y olay send sand clay sand clay sand clay and clay and clay and clay and clay	r-soft and c to 3/ and c and c gravel gravel	atre	ake.	
157 185 1212 1420 1426 1475 1486 1522	i when ir from sta- ma per mi one per mi	perforation of water pum of 57 157 129 420 425 456 475 462 456 504 522 528	of any change of	83 Set first int Set comple 29 y clay send clay sand clay and clay and clay and clay and clay and clay	and c to 3/ and c and c gravel gravel slay /4" gr	atre	aks.	
157 157 1212 1420 1426 1434 1456 1462 1475 1486 1522 1528	i when ir from sta- ma per mi one per mi	perforation of water pure pure pure pure pure pure pure pu	of any change of	83 Set first int Cost comple 29 y olay y olay send sand clay sand clay and clay and clay and clay and clay and sand clay and sand clay and sand sand sand sand sand sand sand	r-soft and c to 3/ and c and c gravel gravel clay / nome	atre	ake.	
mating is below in the below in	i when ir from sta- ma per mi one per mi	perforation of water pum of 57 157 129 420 425 456 475 462 456 504 522 528	of any change of	83 Set first int Cost comple 29 y olay y olay send sand clay sand clay and clay and clay and clay and clay and sand clay and sand clay and sand sand sand sand sand sand sand	and c to 3/ and c and c gravel gravel slay /4" gr	atre	ake.	

Well No. 2

Forma	ATHOR SIZE of W		
	re to 65	n Sandy clay	
65	·· · <u> </u>	Bandy olay-soft streaks.	الزار المستحسب
157	185	Fine sand	· · · · · · · · · · · · · · · · · · ·
185	<u>512</u>	Blue sand and olay	
212	420	Blue clay.	<u>~</u>
420	428	" Fine sand to 3/8" gravel.	
<u>428</u>	<u>434</u>	Blue sand and clay	
434	456	Blue clay.	
456	462	Fine sand and olay.	100
462	·· ·· <u> </u>	Blue clay	
475	482	Sand and gravel to l".	
-485	486	Clay and gravel.	, , , , , , , , , , , , , , , , , , ,
486	504	Sand and gravel to 2".	***********
504	522	Sand and clay	<u>; : </u>
522	528	Band to 3/4" gravel.	
528	533		
533	538		··········· ,
538	·· ·· 545	· · · · · · · · · · · · · · · · · · ·	·
545	600	" Band and clay " Bandy olay	· ·
		" Danty OTBY	
	* **	***************************************	··········
***************************************	* **	# 1 10000000000000000000000000000000000	
***************************************	· · · · · · · · · · · · · · · · · · ·	. I f	
	· "		***************************************
······································	• • •		~~~
	· · ·		
	*	E /	
···································	• ••	4 8	
	· ''	4 (···
		# { 	
	4 1 f	**	
	· ··	46	
	• ••	8 +	
		wors out off, state how cut	*
	arters cas central a		
Depth from a Size of castn	ecit		
Depth from a Size of castn	METACO CHE		
Depth from a Size of casing Lap in larger Was adapter of	casing cannot used?	ft.	
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	g et edapt.
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat		ig of adapts, showing
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	og et ædept- , showing
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	g et edept.
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	g of edapt s showing
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	g et edopi. s showing
Depth from a Size of casing Lap in largor Was adapter of If casing was	conting compatitudes or compat	in. It. paired, state dopth, describe repairs Make describ	g et edopie, showing lines.
Depth from a Size of casts Lap in larger Was adapter of If casing was and condition	cating	paired, state depth, describe repairs Make served at the square affects	g et adapta, showing litera.
Depth from a Size of casin Lap in larger Was adapter of If casing was and condition	cating	paired, state depth, describe repairs Make deresing the separation of the separation	og et adapt a showing liens.
Depth from a Size of casin Lap in larger Was adapter of If casing was and condition	cating	paired, state depth, describe repairs Make deresing the separation of the separation	of edept showing
Depth from a Size of casin Lap in larger Was adapter of If casing was and condition	cating	paired, state depth, describe repairs Make deresing the separation of the separation	of edept showing lines.
Depth from a Size of casin Lap in larger Was adapter o If casing was and condition fs well straigh If not, what	cating cating cannot used? swedged or rouse which casing the case of the casing the	paired, state dopth, describe repairs Make describe was left and probable future effect; **Practically.**	of edepts showing lines.
Depth from a Size of castin Lap in larger Was adapter o If casting was and condition La well straight If not, what Will there be	cating. cat	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically.	of edepts showing lines.
Depth from a Size of castin Lap in larger Was adapter of If casting was and condition La well straight If not, what If so, what of	cating cating cannot used? swedged or rouse which casing the case of the casing the	priced, state depth, describe repairs Make developed at left and probable future effect; and probable future effect; all had probable future effect on pump?. None	of electric shortes
Depth from a Size of castin Lap in larger Was adapter of If casting was and condition La well straight If not, what If so, what of	casing. casing. casing. r camait used?. s swedged or ro in Which casing it, top to bottom to the variation? any dotrimental	priced, state depth, describe repairs Make and left and probable fature effect; **Practically.** **Practically.** **Mone of pump?	of elepi- ty showing lines.
Depth from a Size of castin Lap in larger Was adapter of If casting was and condition La well straight If not, what If so, what of	casing. casing. casing. r camait used?. s swedged or ro in Which casing it, top to bottom to the variation? any dotrimental	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically.	of electrical shortest and the shortest
Depth from a Size of castn Lap in larger Was adapter of If casing was and condition and condition to the Well straight of the Lap was a wall straight of the Lap what a wall there he lif so, what a	cating. cating. cating. cating. cating. cament used?. s swedged or ro in which casing it, top to bottom is the variation? say dottimental	priced, state dopth, describe repairs Make derocic state dopth, describe repairs Make derocic states and probable fature effect; states and probable fature	of edept showing lines.
Depth from a Size of castn Lap in larger Was adapter of If castng was and condition Is well straight ff not, what If so, what as	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	paired, state dopth, describe repairs Make derveit was left and probable future effect; Practically. None	
Depth from a Size of castn Lap in larger Was adapter of If castng was and condition Is well straight ff not, what If so, what as	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	priced, state dopth, describe repairs Make derocic state dopth, describe repairs Make derocic states and probable fature effect; states and probable fature	
Depth from a Bise of castn Lap in larger Was adapter of If casing was and condition Is well straight If not, what If so, what a	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically. Mone was left and probable future effect; None	
Depth from a Bise of castn Lap in larger Was adapter of If casing was and condition Is well straight If not, what If so, what a	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	paired, state dopth, describe repairs Make derveit was left and probable future effect; Practically. None	
Depth from a Bise of castn Lap in larger Was adapter of If casing was and condition Is well straight If not, what If so, what a	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically. Mone was left and probable future effect; None	
Depth from a Bise of castn Lap in larger Was adapter of If casing was and condition Is well straight If not, what If so, what a	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically. Mone was left and probable future effect; None	
Depth from a Bise of castn Lap in larger Was adapter of If casing was and condition Is well straight If not, what If so, what a	continue continue continue continue commit used? If commit used? If commit used? In which casing It top to bottom It top to bottom It to variation?	prired, state dopth, describe repairs Make describe was left and probable future effect; Practically. Mone was left and probable future effect; None	
Depth from a Size of castin Lap in larger Was adapter of resing was about the condition and condition and condition are self to the condition of the condition will thore be self to the condition to the condition of the conditio	cat	priced, state dopth, describe repairs Make developed at the every disease. Practically. Practically. Money of future value. So of future value.	
Depth from a size of castin Lap in larger Was adapter of realing was adapter of the condition and condition and condition and condition was side of the condition of the condition will thore be set so, what a size of the condition will thore be set so, what a size of the condition of the conditi	cat	prired, state depth, describe repairs Make development and probable fature effect; Practically. Practically. None may be of future value. 596!	The contact of the co
Depth from a size of castin Lap in larger Was adapter of realing was adapter of the condition and condition and condition and condition was side of the condition of the condition will thore be set so, what a size of the condition will thore be set so, what a size of the condition of the conditi	cat	priced, state dopth, describe repairs Make developed at the every disease. Practically. Practically. Money of future value. So of future value.	The contact of the co
Depth from a size of castin Lap in larger Was adapter of realing was adapter of the condition and condition and condition and condition was side of the condition of the condition will thore be set so, what a size of the condition will thore be set so, what a size of the condition of the conditi	cat	prired, state depth, describe repairs Make development and probable fature effect; Practically. Practically. None may be of future value. 596!	The contract of the contract o
Depth from a size of castin Lap in larger Was adapter of resing was adapter of resing was and condition and condition will thought the size of the condition will thought the condition will thought the condition of the condition of reports the condition of the c	cat cat cating cating or coment used? If the swedged or rouse in which casing in which casing it, top to bottom is, top to bottom is the variation? Say dottimental it is roport as well septor.	prired, state depth, describe repairs Make development and probable fature effect; Practically. Practically. None may be of future value. 596!	The contract of the contract o

(Defense Plants Corporation)

ROSCOE MOSS COMPANY

3

MELL CO	NTRACTO	DRS TYSE	Log Angeles. Cal RENTAL TOOLS
		8 5	must to Aluminum Company of America.
or Los	Angel	es, Ca	
Exact Loc	# PA P		d Normandle Ave. Los Angeles Galif
Started W	OFE	×	1942
Completed	TT 06.2	ugust	29, 1942
Total dopt	<u>, 600</u>		Bise of shoe
600	fz. of	14 .	nch 10 MOG gauge cusing used Brid left in Well
***************************************			1111 11 11 11 11 11 11 11 11 11 1
	''		***** ** ** ** ** ** ** ** ** ** *
**************	· · · ·		يكري براقة الراق المع <u>مستمسيد</u> كان الراق الما المع المعتبيرين المع وقع وقد المراز الله المستمسيد المعتبيرين المعتبيرين المعتبيرين المعتبيرين المعتبيرين المعتبيرين المعتبيرين المع
 			
		. Wyd	raulio
	erforator (538 to 8 Boles per 14 (nelses
Perforate	516		478 8 4 4 4 6
11	433	40 4	427 8 4
••	tarras and afficient	• • •	64
••			10 11 11 11
		•••	

••			44 44 44 14 14 14 14 14 14 14 14 14 14 1
16			
**			
·			11
••			***************************************
**		****	***************************************
••			44 14
			11 11 11 11
**		••	Make diagram of por-
Diameter	of Perfor	tions	5/16 inches shewing allnessiess.
		0E4	1-3/4 "
			10 mi 1 m
		e perforati	
Standing	lavel after	perforatin	., 83
Note balo	a your obs	ervation of	any change in water level while drilling
***********		*****	the state of the s

Mater la	val whon S	DOSTADA SEL	Toot 83
DISM GO.	was from st	evel patha	**
-		-	ed when Test dist started 1275
-			77
		letton of T	res travel—
O	fe to	3	top soil
3		68	., Olay
68		118	Sandy clay-soft streaks
118	··	122	Fine brown sand
122	,, ,,	134	Brown sandy olay
134	. ,, ,,	153	Blue clay-streaks sand.
153		187	Fine blue sand,
187		214	Blue sandy clay
214		316	Blue clay
316		324	Blue olay-1/4" embedded grayel.
324		330	Blue clay
330		333	Blue clay 1/4" embedded gravel.
333		418	Blue clay
418		424	Fine muddy sand some 1/4" to 1/2
			gravel.
1421	<u>-</u> ., ,,	432	Fine sand to 3/8" clay
1122		127	Fine sand and olav

Well No. 3

0		Atter are rest.
	ш <u>3</u> ., 68	Top soil Glay
68	118	
118	122	Bandy clay-soft streaks
122	-	Fine brown sand
	134	Brown sandy clay
34	153	Blue clay-streaks sand.
153	187	Fine blue sand.
187	214	Blue sandy clay
214	316	Blue clay
316	324	71
324	330	Slue clay-1/4" embedded gravel Blue clay
330		~
333 "	. 333 . 418	
	424	Blue clay
418		Fine muddy sand some 1/4" to 1/2"
		. gravel.
<u>424</u>	432	Fine sand to 3/8" clay
432 "	437	. Fine sand and olay
_ 437	460	Blue sandy clay
460	470	. Fine sand and olay
470	474	Blue clay
474	482	
482		. Sand and gravel to 1".
	· <u>495</u>	Band and gravel to 3/4"
495	515	. Band and gravel to 2".
515	519	. Sand and gravel to 1/2" Muddy
519	536	Fine sand and olay.
536	547	. Sand and gravel to 14.
547	573	. Fine sandy clay.
<u>. 573</u>	600	Blue olay.
		A
44	***************************************	
***************************************	***************************************	
	<u> </u>	
** **		·

	, ,	4
If reducing string	is of casing w	ere cut of, state dow cut
		ere cut off, state dow cut
Depth from surfa	ce cut	ere cut off, state how cut
Depth from surfa Size of pasing cu	es rut	
Depth from surfa Size of casing cu Lap in larger cas	ce cut	
Depth from surfa Size of sizing cu Lap in larger caa Was adaptes or co	es cut ting	The state of the s
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	ired, state dopth, describe repairs Natio describe of adapt
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	The state of the s
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	ired, state dopth, describe repairs Natio describe of adapt
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	ired, state dopth, describe repairs Natio describe of adapt
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	ired, state dopth, describe repairs Natio describe of adapt
Depth from surfa Size of ceaing cu Lap in larger cas Was adapter or co If casing was sw	ing	ired, state dopth, describe repairs Natio describe of adapt
Depth from surfa- Size of pasing cu Lap in larger caa. Was adapter or co If casing was sw and condition in t	ce cut ing mens wod7 redged or repr which casing 4	in. Action thereing of desprise state depth, describe repairs action agrams, showing at desprise in a agrams, showing dimensions.
Depth from surfa- fire of pasing ou Lap in larger can Was adapter or con If casing was sw and condition in v	ce cut ing mens wod? redged or rep which casing a	in. ft. aired, state dopth, describe repairs: Make disputation of the square, showing of adoption of the square, showing dimensions. Practically.
Depth from surfa- fire of pasing ou Lap in larger can Was adapter or con If casing was sw and condition in v	ce cut ing mens wod? redged or rep which casing a	in. ft. aired, state dopth, describe repairs: Make disputation of the square, showing of adoption of the square, showing dimensions. Practically.
Depth from surfa- fire of pasing ou Lap in larger can Was adapter or con If casing was sw and condition in v	ce cut ing mens wod? redged or rep which casing a	in. ft. aired, state dopth, describe repairs: Make disputation of the square, showing of adoption of the square, showing dimensions. Practically.
Depth from surfa- fire of pasing ou Lap in larger can Was adapter or con If casing was sw and condition in v	ce cut ing mens wod? redged or rep which casing a	in. ft. aired, state dopth, describe repairs: Make disputation of the square, showing of adoption of the square, showing dimensions. Practically.
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or cas If casing was sw and condition in 1 Lap in larger case If casing was sw and condition in 1 Lap in lap in lap Lap	ce cut ting mens wed? redged or repr redged correspond bich casing a prich casing a correspond or to bottom?	in. in. Aired, state depth, describe repairs: Make depoint of lie agrams, showing of linearism. Was laft and probable future effect: Practically.
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or on If casing was sw and condition in the Condition in th	ing	in. Aired, state depth, describe reputre of the square, shewing of adoption of the square, shewing dimensions. Practically. Rect as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or cas If casing was sw and condition in 1 Lap in larger case If casing was sw and condition in 1 Lap in lap in lap Lap	ing	in. Aired, state depth, describe reputre of the square, shewing of adoption of the square, shewing dimensions. Practically. Rect as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca- if casing was aw and condition in a and condition in a is well straight, ac if not, what is th Will there be any if so, what effect;	ce cut ing	aired, state depth, describe repairs Motio depoins of adoption is in depoins of the depoins of the depoins of the depoint of t
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca- if casing was aw and condition in a and condition in a is well straight, ac if not, what is th Will there be any if so, what effect;	ce cut ing	in. Aired, state depth, describe reputre of the square, shewing of adoption of the square, shewing dimensions. Practically. Rect as pump? None
Depth from surfa- Size of casing ou Lap in larger can Was adapter or on If casing was aw and condition in a and condition in a the well straight, so If not, what is th will there be any If so, what effects	ce cut ing mens word? redged or repr which casing a by to bottom? to variation?	aired, state depth, describe reputre of the square, showing of adoption of the square, showing dimensions. Practically. Rect as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe reputre of the square, showing of adoption of the square, showing dimensions. Practically. Rect as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of casing ou Lap in larger cas Was adapter or ca If casing was aw and condition in a and condition in a the well straight, to If not, what is th will there be any If so, what effect?	ce cut ing ing mens wod7 redged or repr which casing a prop to bottom? detrimental af	aired, state depth, describe repairs of the square, showing a step of the square, showing dimensions. Practically. Pract as pump? None
Depth from surfa- Size of pasing on Lap in larger can Was adapted or co. If casing was aw and condition in the condition in the is well straight, to If not, what is the Will there be any If so, what offect?	ce cut ing	practically. Practically. None None Ted to 5961
Depth from surfa- Size of pasing ou Lap in larger can Was adapter or ca- If casing was aw and condition in a and condition in a law well straight, to If not, what is th Will there be any If so, what effect; Sive any additional Combit Plug	ce cut ing	in. It. Sired, state depth, describe repairs Motio thereing a storp of its square showing dimensions. Practically. Practically. Rect as pump? None Profresses and report must be complete for its recessor.
Depth from surfa- Size of pasing ou Lap in larger can Was adapter or ca- If casing was aw and condition in a and condition in a law well straight, to If not, what is th Will there be any If so, what effect; Sive any additional Combit Plug	ce cut ing	practically. Practically. None None Ted to 5961
Depth from surfa- Size of pasing ou Lap in larger can Was adapter or ca- If casing was aw and condition in a and condition in a law well straight, to If not, what is th Will there be any If so, what effect; Sive any additional Combit Plug	ce cut ing	in. It. Sired, state depth, describe repairs Motio thereing a storp of its square showing dimensions. Practically. Practically. Rect as pump? None Profresses and report must be complete for its recessor.
Depth from surfa- Size of pasing ou Lap in larger can Was adapter or ca- If casing was aw and condition in a and condition in a law well straight, to If not, what is th Will there be any If so, what effect; Sive any additional Combit Plug	ce cut ing	progressee and report must be complete for his successor. Der 2, 1942.



APPENDIX 3 VIDEO SURVEY LOG SUMMARIES

VIDEO SURVEY LOG BRC WELL NO. 2 JULY 23, 1998

Depth (ft*)	Observed Casing Conditions
0 to 106	Blank casing with minor oil stains to 10 ft bgs. Casing joints every 4 feet.
	Noted sounding tube near ground surface.
106	Water surface, clear, no oil, no organic matter.
130, 167	Growths visible, minor scale below 130 ft.
175	Growths increasing, some cloudiness of water.
215-225	Water very cloudy, Casing walls barely visible. Water clears at little 225 ft.
258	Water becomes cloudy again and casing wall barely visible. Abundant
	biomass in water column.
305	Water clears slightly.
477	Side scan reveals top of perforations.
506	Hard to discern bottom of perforations.
525	Top of next set of perforations.
530, 535	Hard to discern bottom and top of perforations, at 530 and 535 ft
	respectively.
539-540	Bottom of perforations.
544	Fade to black, sediment fill.

*Note: (1) Depths are measured from ground surface at side scan camera, which is 2-feet above back of light. Numbers above corrected. Video survey performed by Water Well Redevelopers of Anaheim.

VIDEO SURVEY LOG BRC WELL NO. 3 JULY 9, 1998

Depth (ft*)	Observed Casing Conditions
0 to 106	Blank casing with abundant scale. Casing joints every 4 feet.
106	Water surface, clear, no oil, no organic matter. Light scale on casing. Water clarity good.
423	Top of perforations.
423 to 445	Water clarity generally poor.
445,453,465	Side scans show blank casing.
475	Within next set of perforations.
483	Fade to black, sediment fill. Still in perforations.

*Note: (1) Depths are measured from ground surface at side scan camera, which is 2-feet above back of light. Numbers above corrected. Video survey performed by Water Well Redevelopers of Anaheim.



APPENDIX 4
RESULTS OF LABORATORY ANALYSIS
OF WELL BOTTOM SEDIMENT SAMPLES



RESULTS OF LABORATORY ANALYSIS WELL NO. 3



nn Ave., Irvine, CA 92606 te A. Coiton, CA 92324 1014 E. Cooley L

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406

(818) 779-1844 FAX (818) 779-18 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-34

(714) 261-1022 FAX (714) 261-12 (909) 370-4667 FAX (909) 370-104

Client Project ID: S9508 Sampled: Jul 13, 1998 Received: Jul 13, 1998 Sample Descript: Soil, Soil/Sand Well #3 Extracted: Jul 14, 1998 Lab Number: HG01501 Analyzed: Jul 14, 1998 QC Batch: HG14071S Reported: Jul 15, 1998

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606 Attention: R. Slade

VOLATILE ORGANICS by GC/MS (EPA 8260)

Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
Benzene	2.0	N.D.	Ethylbenzene	2.0	N.D.
Bromobenzene	5.0	N.D.	Hexachlorobutadiene	5.0	N.D.
Bromochloromethane	5.0	N.D.	Isopropylbenzene		N.D.
Bromodichloromethane	2.0	N.D.	p-Isopropyltoluene		N.D.
Bromoform	5.0	N.D.	Methylene chloride	20	N.D.
Bromomethane	5.0	N.D.	Naphthalene		N.D.
n-Butylbenzene	5.0	N.D.	n-Propylbenzene	2.0	N.D.
sec-Butylbenzene	5.0	N.D.	Styrene	2.0	N.D.
tert-Butylbenzene	5.0	N.D.	1,1,1,2-Tetrachloroethane	5.0	N.D.
Carbon tetrachloride	5.0	N.D.	1,1,2,2-Tetrachloroethane	2.0	N.D.
Chlorobenzene	2.0	N.D.	Tetrachloroethene	2.0	N.D.
Chloroethane	5.0	N.D.	Toluene	2.0	N.D.
Chloroform	2.0	3.6	1,2,3-Trichlorobenzene	5.0	N.D.
Chloromethane	5.0	N.D.	1,2,4-Trichlorobenzene	5.0	N.D.
2-Chlorotoluene	5.0	N.D.	1,1,1-Trichloroethane	2.0	N.D.
4-Chlorotoluene	5.0	N.D.	1,1,2-Trichloroethane	2.0	N.D.
Dibromochloromethane	2.0	N.D.	Trichloroethene	2.0	N.D.
1,2-Dibromo-3-chloropropane	5.0	N.D.	Trichlorofluoromethane	5.0	N.D.
1,2-Dibromoethane	2.0	N.D.	1,2,3-Trichloropropane	10	N.D.
Dibromomethane	2.0	N.D.	1,2,4-Trimethylbenzene	2.0	N.D.
1,2-Dichlorobenzene	2.0	N.D.	1,3,5-Trimethylbenzene	2.0	N.D.
1,3-Dichlorobenzene	2.0	N.D.	Vinyl chloride	5.0	N.D.
1,4-Dichlorobenzene	2.0	N.D.	o-Xylene	2.0	N.D.
Dichlorodifluoromethane	5.0	N.D.	m,p-Xylenes	2.0	N.D.
1,1-Dichloroethane	2.0	N.D.			
1,2-Dichloroethane	2.0	N.D.			
1,1-Dichloroethene	5.0	N.D.		÷	
cis-1,2-Dichloroethene	2.0	N.D.			
trans-1,2-Dichloroethene	2.0	N.D.			
1,2-Dichloropropane	2.0	N.D.			
1,3-Dichloropropane	2.0	N.D.			
2,2-Dichloropropane	2.0	N.D.			
1,1-Dichloropropene	2.0	N.D.			
cis-1,3-Dichloropropene	2.0	N.D.			
Amount 4 9 Dishlamananana	0.0				

Analytes reported as N.D. were not present at or above the reporting limit.

2.0

DEL MAR ANALYTICAL (ELAP #1197)

trans-1,3-Dichloropropene.......

Patty Mata Project Manager

Surrogate Standard Recoveries (Accept.	Limits):
Dibromofluoromethane (80-120)	99%
Toluene-d8 (81-117)	104%
4-Bromofluorobenzene (74-121)	98%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

N.D.

HG01501.RCS <1 of 9>

R. C. Slade & Associates

North Hollywood, CA 91606

6442 Coldwater Canyon

Attention: R. Slade

2852 ** an Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1014 E. Cooley L

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-

2465 W. 12th St., Suite 1, Tempe, AZ 85281

ite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-

(602) 968-8272 FAX (602) 968-

Extracted: Jul 14, 1998 Analyzed: Jul 14, 1998 Reported: Jul 15, 1998

Method Blank

QC Batch:

HG14071S

VOLATILE ORGANICS by GC/MS (EPA 8260)

			(
Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
Benzene Bromobenzene Bromochloromethane Bromodichloromethane Bromoform Bromomethane n-Butylbenzene sec-Butylbenzene tert-Butylbenzene Carbon tetrachloride Chlorobenzene Chloroethane Chloroform Chloromethane 2-Chlorotoluene Dibromochloromethane 1,2-Dibromo-3-chloropropane 1,2-Dibromoethane 1,2-Dichlorobenzene 1,4-Dichlorobenzene 1,4-Dichloroethane 1,1-Dichloroethane 1,1-Dichloroethane 1,1-Dichloroethane 1,1-Dichloroethene 1,2-Dichloroethene 1,1-Dichloroethene 1,2-Dichloropropane 1,2-Dichloropropane 1,2-Dichloropropane 1,2-Dichloropropane 1,2-Dichloropropane 1,2-Dichloropropane 1,3-Dichloropropane 1,3-Dichloropropane 1,1-Dichloropropane 1,1-Dichloropropane 1,1-Dichloropropane 1,1-Dichloropropane 1,1-Dichloropropane	2.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5	(PPO) N.D. N.D. N.D. N.D. N.D. N.D. N.D. N.D	Ethylbenzene	(ppb) 2.0 5.0 2.0 2.0 2.0 5.0 2.0 2.0 2.0 2.0 2.0 2.0 2.0 2.0 2.0 2	
trans-1,3-Dichloropropene	2.0	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

Surrogate Standard Recoveries (Accept	t. Limits);
Dibromofluoromethane (80-120)	103%
Toluene-d8 (81-117)	103%
4-Bromofluorobenzene (74-121)	96%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <6 of 9>



R. C. Slade & Associates

6442 Coldwater Canyon

Attention: R. Slade

North Hollywood, CA 91606

2852 ** on Ave., Irvine, CA 92606 1014 E. Cooley L ite A, Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406

2465 W. 12th St., Suite 1, Tempe, AZ 85281

Reported:

(818) 779-1844 FAX (818) 779-1 (602) 968-8272 FAX (602) 968-3

(714) 261-1022 FAX (714) 261-1

(909) 370-4667 FAX (909) 370-1

Jul 16, 1998

Client Project ID: S9508 Sampled: Jul 13, 1998 Received: Jul 13, 1998 Sample Descript: Soil, Soil/Sand Well #3 Extracted: Jul 14, 1998 Lab Number: HG01501 Analyzed: Jul 16, 1998 QC Batch:

SEMI-VOLATILE ORGANICS by GC/MS (EPA 3550/8270)

HG14SE1S

Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
Acenaphthene	100	N.D.	Dimethyl phthalate	100	N.D.
Acenaphthylene	100	N.D.	4,6-Dinitro-2-methylphenol	250	N.D.
Aniline	150	N.D.	2,4-Dinitrophenol	250	N.D.
Anthracene	100	N.D.	2,4-Dinitrotoluene	100	N.D.
Azobenzene	150	N.D.	2,6-Dinitrotoluene	100	N.D.
Benzidine	1,000	N.D.	Di-N-octyl phthalate	500	N.D.
Benzoic Acid	500	N.D.	Fluoranthene	100	N.D.
Benz(a)anthracene	100	N.D.	Fluorene	100	N.D.
Benzo(b)fluoranthene	200	N.D.	Hexachlorobenzene	100	N.D.
Benzo(k)fluoranthene	200	N.D.	Hexachlorobutadiene	100	N.D.
Benzo(g,h,i)perylene	150	N.D.	Hexachlorocyclopentadiene.	500	N.D.
Benzo(a)pyrene	200	N.D.	Hexachloroethane	200	N.D.
Benzyl alcohol	200	N.D.	Indeno(1,2,3-cd)pyrene	200	N.D.
Bis(2-chloroethoxy)methane	100	N.D.	Isophorone	100	N.D.
Bis(2-chloroethyl)ether	100	N.D.	2-Methylnaphthalene	100	N.D.
Bis(2-chloroisopropyl)ether	100	N.D.	2-Methylphenol	150	N.D. N.D.
Bis(2-ethylhexyl)phthalate	1,000	N.D.	4-Methylphenol	150	N.D. N.D.
4-Bromophenyl phenyl ether	150	N.D.	Naphthalene	150	N.D. N.D.
Butyl benzyl phthalate	500	N.D.	2-Nitroaniline	200	N.D. N.D.
4-Chloroaniline	100	N.D.	3-Nitroaniline	200	N.D.
2-Chloronaphthalene	100	N.D.	4-Nitroaniline	500	N.D. N.D.
4-Chloro-3-methylphenol	100	N.D.	Nitrobenzene	500	N.D. N.D.
2-Chlorophenol	250	N.D.	2-Nitrophenol.	100	N.D. N.D.
4-Chlorophenyl phenyl ether	100	N.D.	4-Nitrophenol	500	N.D.
Chrysene	100	N.D.	N-Nitrosodiphenylamine	200	N.D. N.D.
Dibenz(a,h)anthracene	250	N.D.	N-Nitroso-di-N-propylamine.	150	N.D. N.D.
Dibenzofuran	100	N.D.	Pentachlorophenol	500	N.D. N.D.
Di-N-butyl phthalate	250	N.D.	Phenanthrene	100	N.D. N.D.
1,3-Dichlorobenzene	100	N.D.	Phenol	150	N.D. N.D.
1,4-Dichlorobenzene	100	N.D.	Pyrene	150	N.D. N.D.
1,2-Dichlorobenzene	100	N.D.	1,2,4-Trichlorobenzene	100	
3,3-Dichlorobenzidine	500	N.D.	2,4,5-Trichlorophenol	150	N.D. N.D.
2,4-Dichlorophenol	100	N.D.	2,4,6-Trichlorophenol	150	
Diethyl phthalate	100	N.D.	-, 40 monoropheno	เอด	N.D.
2,4-Dimethylphenol	250	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata

Project Manager

Surrogate Standard Recoveries (Accept. Limits): 2-Fluorophenol (25-121)...... 49% Phenol-d6 (24-113)..... 60% 2,4,6-Tribromophenol (19-122) 59% Nitrobenzene-d5 (23-120)...... 51% 2-Fluorobiphenyl (30-115)...... 57% Terphenyl-d14 (18-137)..... 68%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <2 of 9>

2852 * M Ave., Irvine, CA 92606 1014 E. Cooley L te A, Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(714) 261-1022 FAX (714) 261-1 (909) 370-4667 FAX (909) 370-1 (818) 779-1844 FAX (818) 779-1

(602) 968-8272 FAX (602) 968-3

Extracted: Jul 14, 1998 Analyzed: Jul 16, 1998 Reported: Jul 16, 1998

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606 Attention: R. Slade Method Blank

SEMI-VOLATILE ORGANICS by GC/MS (EPA 3550/8270)

Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
Acenaphthene	100	N.D.	Dimethyl phthalate	100	•
Acenaphthylene	100	N.D.	4,6-Dinitro-2-methylphenol	250	N.D.
Aniline	150	N.D.	2,4-Dinitrophenol	250 250	N.D.
Anthracene	100	N.D.	2,4-Dinitrotoluene	100	N.D.
Azobenzene	150	N.D.	2,6-Dinitrotoluene	100	N.D.
Benzidine	1,000	N.D.	Di-N-octyl phthalate		N.D.
Benzoic Acid	500	N.D.	Fluoranthene	500	N.D.
Benz(a)anthracene	100	N.D.	Fluorene	100	N.D.
Benzo(b)fluoranthene	200	N.D.	Hexachlorobenzene	100	N.D.
Benzo(k)fluoranthene	200	N.D.	Hexachlorobutadiene.	100	N.D.
Benzo(g,h,i)perylene	150	N.D.	Hexachlorocyclopentadiene.	100	N.D.
Benzo(a)pyrene	200	N.D.	Hexachloroethane	500	N.D.
Benzyl alcohol	200	N.D.	Indeno(1,2,3-cd)pyrene	200	N.D.
Bis(2-chloroethoxy)methane	100	N.D.	Isophorono	200	N.D.
Bis(2-chloroethyl)ether	100	N.D.	Isophorone2-Methylnaphthalene	100	N.D.
Bis(2-chloroisopropyl)ether	100	N.D.	2-Methylphonol	100	N.D.
Bis(2-ethylhexyl)phthalate	1,000	N.D.	2-Methylphenol	150	N.D.
4-Bromophenyl phenyl ether	150	N.D.	4-Methylphenol	150	N.D.
Butyl benzyl phthalate	500	N.D.	Naphthalene	150	N.D.
4-Chloroaniline	100	N.D.	2-Nitroaniline	200	N.D.
2-Chloronaphthalene	100	N.D.	3-Nitroaniline	200	N.D.
4-Chloro-3-methylphenol	100	N.D.	4-Nitroaniline	500	N.D.
2-Chlorophenol	250	N.D.	Nitrobenzene	500	N.D.
4-Chlorophenyl phenyl ether	100	N.D.	2-Nitrophenol	100	N.D.
Chrysene	100	N.D.	4-Nitrophenol	500	N.D.
Dibenz(a,h)anthracene	250	N.D.	N-Nitrosodiphenylamine	200	N.D.
Dibenzofuran	100	N.D.	N-Nitroso-di-N-propylamine.	150	N.D.
Di-N-butyl phthalate	250	N.D.	Pentachlorophenol	500	N.D.
1,3-Dichlorobenzene	100	N.D.	Phenanthrene	100	N.D.
1,4-Dichlorobenzene	100	N.D.	Phenol	150	N.D.
1,2-Dichlorobenzene	100	N.D.	Pyrene	150	N.D.
3,3-Dichlorobenzidine	500	N.D. N.D.	1,2,4-Trichlorobenzene	100	N.D.
2,4-Dichlorophenol	100	N.D.	2,4,5-Trichlorophenol	150	N.D.
Diethyl phthalate	100	N.D.	2,4,6-Trichlorophenol	150	N.D.
2,4-Dimethylphenol	250				
,	200	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

Surrogate Standard Recoveries (Accep	t. Limits):
2-Fluorophenol (25-121)	49%
Phenol-d6 (24-113)	57%
2,4,6-Tribromophenol (19-122)	65%
Nitrobenzene-d5 (23-120)	46%
2-Fluorobiphenyl (30-115)	57%
Terphenyl-d14 (18-137)	84%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <7 of 9>

2852 Africh Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1 1014 E. Cooley & te A. Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suité 1, Tempe, AZ 85281

(909) 370-4667 FAX (909) 370-1 (602) 968-8272 FAX (602) 968-3

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606

Attention: R. Slade

Client Project ID: \$9508

Lab Number:

Sample Descript: Soil, Soil/Sand Well #3

HG01501

Sampled: Jul 13, 1998 Received: Jul 13, 1998 Extracted: Jul 14, 1998 Analyzed: Jul 14, 1998 Reported: Jul 15, 1998

CALIFORNIA CODE OF REGULATIONS, TITLE 22 METALS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/Kg (ppm)		TTLC Sample Result mg/Kg (ppm)
Antimony	6010	15	500	10	•••••	11
Arsenic	6010	5.0	500	2.0	•	6.2
Barium	6010	100	10000	1.0		5.2
Beryllium	6010	0.75	75	0.50	***************************************	N.D.
Cadmium	6010	1.0	100	0.50		2.5
Chromium, total	6010	5.0	2500	1.0	••••••	97
Cobalt	6010	80	8000	1.0	••••••	12
Copper	6010	25	2500	1.0	***************************************	300
Lead	6010	5.0	1000	2.0		6.3
Mercury	7471	0.20	20	0.020		0.025
Molybdenum	6010	350	3500	2.0		15
Nickel	6010	20	2000	1.0		190
Selenium	6010	1.0	100	2.0		N.D.
Silver	6010	5.0	500	1.0		N.D.
Thallium	6010	7.0	700	10		N.D.
Vanadium	6010	24	2400	1.0		1.1
Zinc	6010	250	5000	5.0		24

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <3 of 9>

R. C. Slade & Associates

2852 / ' on Ave., Irvine, CA 92606 1014 E. Cooley C ite A. Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 [818] 779-1844 FAX [818] 779-1

(714) 261-1022 FAX (714) 261-1 (909) 370-4667 FAX (909) 370-1

2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX [602] 968-3

Extracted: Jul 14, 1998 Analyzed: Jul 14, 1998 Reported: Jul 15, 1998

6442 Coldwater Canyon North Hollywood, CA 91606 Method Blank Attention: R. Slade

CALIFORNIA CODE OF REGULATIONS, TITLE 22 METALS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/Kg (ppm)		TTLC Sample Result mg/Kg (ppm)
Antimony	6010	15	500	10	***************************************	N.D.
Arsenic	6010	5.0	500	2.0		N.D.
Barium	6010	100	10000	1.0	***************************************	N.D.
Beryllium	6010	0.75	75	0.50		N.D.
Cadmium	6010	1.0	100	0.50		N.D.
Chromium, total	6010	5.0	2500	1.0		N.D.
Cobalt	6010	80	8000	1.0		N.D.
Copper	6010	25	2500	1.0		N.D.
Lead	6010	5.0	1000	2.0		N.D.
Mercury	7471	0.20	20	0.020	•	N.D.
Molybdenum	6010	350	3500	2.0		N.D.
Nickel	6010	20	2000	1.0		N.D.
Selenium	6010	1.0	100	2.0		N.D.
Silver	6010	5.0	500	1.0		N.D.
Thallium	6010	7.0	700	10		N.D.
Vanadium	6010	24	2400	1.0	***************************************	N.D.
Zinc	6010	250	5000	5.0		N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <8 of 9>



2852 * In Ave., Irvine, CA 92606 [714] 261-1022 FAX (714) 261-1014 E. Cooley L

ite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(602) 968-8272 FAX (602) 968-

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606 Attention: R. Slade

Client Project ID: S9508

Sample Descript: Soil First Sample #: HG01501

Sampled: Jul 13, 1998 Received: Jul 13, 1998 Extracted: Jul 15, 1998 Analyzed: Jul 15, 1998 Reported: Jul 15, 1998

CHROMIUM VI (EPA 7196)

Laboratory Number	Sample Description	Reporting Limit mg/Kg (ppm)	Sample Result mg/Kg (ppm)
HG01501	Soil/Sand Well #3	0.50	N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <5 of 9>



2852 Att 5n Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1

1014 E. Cooley C .te A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406

(909) 370-4667 FAX (909) 370-1

(818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(602) 968-8272 FAX (602) 968-3

Extracted: Analyzed:

Reported:

Jul 15, 1998 Jul 15, 1998 Jul 15, 1998

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606 Attention: R. Slade

Method Blank

CHROMIUM VI (EPA 7196)

Reporting Limit mg/Kg (ppm)

Sample Result mg/Kg (ppm)

Method Blank

Sample

Description

0.50

N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata

Project Manager

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <9 of 9>



1014 E. Cooley C ite A. Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1

2465 W. 12th St., Suite 1, Tempe, AZ 85281

2852 ** >n Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1 (909) 370-4667 FAX (909) 370-1

(602) 968-8272 FAX (602) 968-3

Sampled: Jul 13, 1998 Received: Jul 13, 1998

Extracted: Jul 13, 1998 Analyzed: Jul 13, 1998 Reported: Jul 15, 1998

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA 91606 Attention: R. Slade

Client Project ID: S9508

Sample Descript: Soil First Sample #: HG01501

pH (EPA 9045)

Laboratory Number	Sample Description	Reporting Limit pH units	Sample Result pH units
HG01501	Soil/Sand Well #3	N.A.	9.7

DEL MAR ANALYTICAL (ELAP #1855)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01501.RCS <4 of 9>

2852 A" in Ave., Irvine, CA 92606 1014 E. Cooley Di .e A. Colton, CA 92324

16525 Sherman Way. Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1

2465 W. 12th St., Suite 1, Tempe, AZ 85281

(714) 261-1022 FAX (714) 261-1 (909) 370-4667 FAX (909) 370-1

Jul 21, 1998

(602) 968-8272 FAX (602) 968-3

Sampled: Jul 13, 1998 Received: Jul 13, 1998 Extracted: Jul 18, 1998 Analyzed: Jul 21, 1998

Reported:

R. C. Slade & Associates 6442 Coldwater Canyon North Hollywood, CA Attention: R. Slade

Client Project ID: S9508

Lab Number:

Sample Descript: STLC Extract of a Soil, Soil/Sand Well #3 HG01867

LABORATORY ANALYSIS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/L (ppm)	STLC Sample Result mg/L (ppm)
Chromium, total	6010	5.0	2500	0.10	 N.D.
Copper	6010	25	2500	0.10	 1.0
Nickel	6010	20	2000	0.10	 0.29

Prior to analysis, the sample was extracted using the WET method as described in California Title 22, Section 66261, Appendix II. Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01867.RCS <1 of 2>

R. C. Slade & Associates

6442 Coldwater Canyon

North Hollywood, CA

Attention: R. Slade

2852 / ¬ Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1 1014 E. Cooley Dr. .e A, Colton, CA 92324

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1

(909) 370-4667 FAX (909) 370-1

2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-3

Method Blank

Extracted: Jul 18, 1998 Analyzed: Jul 21, 1998 Reported: Jul 21, 1998

LABORATORY ANALYSIS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/L (ppm)		STLC Sample Result mg/L (ppm)
Chromium, total	6010	5.0	2500	0.10	••••••	N.D.
Copper	6010	25	2500	0.10	***************************************	N.D.
Nickel	6010	20	2000	0.10		N.D.

Prior to analysis, the sample was extracted using the WET method as described in California Title 22, Section 66261, Appendix II. Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG01867.RCS <2 of 2>

'n Ave., Irvine, CA 92606 1014 E. Cooley D. ite A, Colton, CA 92324

MEAN

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406

(909) 370-4667 FAX (909) 370-1

(714) 261-1022 FAX (714) 261-1

(818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(602) 968-8272 FAX (602) 968-3

Acceptance

MS/MSD DATA REPORT

METHOD: METALS Instrument: ICP Matrix: Soil

Date

Analyzed:

7/21/98

Sample:

HG01223

Batch:

Analyte

HG18SL2S(A)

R1

	 <i>J</i>	
_	 	

Sp MS MSD PR1 PR2 **RPD** PR Limits ppm ppm ppm ppm % % **RPD MPR**

Chromium Copper Lead * Nickel

0.140	2.0	2.14	2.22	100%	104%	3.67%	102%	20	80-120
0	2.0	2.37	2.46	119%	123%	3.73%	121%	20	80-120
27.2	2.0	30.1	28.4	145%	60%	5.81%	103%		
0.364	2.0	2.45	2.32	104%				20	80-120
لنتك		2.70	2.52	104%	98%	5.45%	101%	20	80-120

^{*} Due to high levels of analyte in the sample, the MS/MSD calculation does not provide useful spike recovery information. See LCS for batch validation.

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD. Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits...... Statistically determined on an annual basis.

2852 Altr e., Irvine, CA 92714 (714) 261-1022 FAX (714) 261 1014 E. Cooley Dr., Sc. A, Colton, CA 92324 (909) 370-4667 FAX (909) 370 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968

ADDITIONAL ANALYSIS REQUEST FORM

i			
Today's Date: 7	Del Mar Analy	tical Project Manager:	(IM
Request via: tele	phone chain of custody for	rm fax transmission	E-mailother
Client: RCS		act: Rr Slade	
Project: $\underline{S95}$	108		
Date Sampled:	7/13/98 Da	te Received: 7/13/	E8
Status: d in progress	• [, ,	
SAMPLE NUMBER	SAMPLE DESCRIPTION	ANALYSIS REQUESTED	SPECIAL REQUIREMENTS
HG01501	Soil/Sand Wolf 3	STRC Cr	
		Cu	
TURNAROUNE	O STATUS:Same Day	-	3days
	5daysStand	lardNo Rush Charg	e

2852 * m Ave., Irvine, CA 92606 [714] 261-1022 FAX (714) 261-1014 E. Cooley D

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-2465 W. 12th St., Suite 1, Tempe, AZ 85281 [602] 968-8272 FAX (602) 968-

ite A. Colton, CA 92324 (909) 370-4667 FAX (909) 370-

MS/MSD DATA REPORT

EPA METHOD: 7471 Matrix: Soil

Date

Analyzed:

7/14/98

Sample:

HG01437

Batch:

HG14HG1S

Analyte	R1	Sp ——	MS	MSD	PR1	PR2	RPD	MEAN PR	Acceptance Limits
	ppm	ppm	ppm	ppm	%	%	%		RPD MPR
Mercury	0.028	0.80	0.812	0.783	98%	94%	3.6%	96%	20 80-120

Definition of Terms:

R1..... Result of Sample Analysis

Sp. Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100

PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD..... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits...... Statistically determined on an annual basis.

Del Mar Analytical

2852 ^ on Ave., Irvine, CA 92606 (714) 261-1022 FAX [714] 261-1 te A, Colton, CA 92324

MEAN

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(909) 370-4667 FAX (909) 370-1 (818) 779-1844 FAX (818) 779-1

(602) 968-8272 FAX (602) 968-3

Acceptance

MS/MSD DATA REPORT

EPA METHOD: 8260 Matrix: Soil

Date

Analyzed:

7/14/98

Sample:

HG01438

Batch:

HG14071S

R1

Sp

MS

MSD

Analyte
Vinyl Chloride
1,1-Dichloroethene
MTBE
1,1-Dichlororethane
Chloroform
1,2-Dichlororethane
Benzene
Trichloroethene
Toluene
Tetrachloroethene
Chlorobenzene
Ethylbenzene
m,p-Xylenes
o-Xylene

K1	Sp	MS	MSD	PR1	PR2	RPD	PR		nits
ppb	ppb	ppb	ppb	%	%	%	%	RPD	MPR
0	25	22	21	88%	84%	4.7%	86%	T 20-	
0	25	25	24	100%	96%	4.1%	 	30	30-160
0	25	25	24	100%		+	98%	40	45-165
0	25	24	24	 	96%	4.1%	98%	40	55-155
0	25			96%	96%	0.0%	96%	20	55-150
	 	24	23	96%	92%	4.3%	94%	20	65-140
0.2	25	22	21	87%	83%	4.7%	85%	30	55-145
0	25	23	23	92%	92%	0.0%	92%	25	60-140
0	25	25	24	100%	96%	4.1%	98%	30	
0	25	24	23	96%	92%	4.3%			60-145
0	25	24	23	96%			94%	20	65-140
0	25	24			92%	4.3%	94%	50	10-200
0			23	96%	92%	4.3%	94%	20	70-135
<u> </u>	25	24	23	96%	92%	4.3%	94%	20	70-140
0	50	48	47	96%	94%	2.1%	95%	20	40-160
0	25	24	24	96%	96%	0.0%	96%		
						0.070	30 /0	20	65-150

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD..... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits...... Statistically determined on an annual basis.

(714) 261-1022 FAX (714) 261-1 (909) 370-4667 FAX (909) 370-1 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1

(602) 968-8272 FAX (602) 968-3

2465 W. 12th St., Suite 1, Tempe, AZ 85281



MS/MSD DATA REPORT

EPA METHOD: 7196A Matrix: Soil

Date

Analyzed:

7/15/98

Sample:

HG01501

Batch:

HG15C61S

Analyte

MEAN Acceptance **R1** Sp MS MSD PR₁ PR₂ PR **RPD** Limits ppm ppm ppm ppm % % % RPD **MPR**

8%

0.0%

8%

20

80-120

Chromium VI

* The MS/MSD recoveries and/or RPD were outside of acceptance limits due to sample matrix effects.

9%

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD...... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

3.33

See LCS for batch validation.

0.295

0.259

Acceptance Limits..... Statistically determined on an annual basis.

te A, Colton, CA 92324 [909] 370-4667 FAX [909] 370-1



16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-3

LCS DATA REPORT

EPA METHOD: 7196A

Date

Analyzed:

7/10/98

Batch:

HG10C61S

Analyte	St	R1	PR	Acceptance Limits
	ppm	ppm	%	%
Chromium VI	3.0	2.4	80%	80-120

Definition of Terms:

St...... Concentration of standard added to blank. R1..... Standard Result PR Percent Recovery of R1; (R1 / St) X 100

Acceptance Limits..... Statistically determined on an annual basis.

2852 Athon Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1 te A, Colton, CA 92324 [909] 370-4667 FAX (909) 370-1 1014 E. Cooley D

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281

[602] 968-8272 FAX (602) 968-5

MS/MSD DATA REPORT

METHOD: METALS Instrument: ICP Matrix: Soil

Date

Analyzed:

7/14/98

Sample:

HG01510

Batch:

HG14ME1S

Analyte	R1	Sp	MS	MSD	PR1	PR2	RPD	MEAN PR		ptance nits
	ppm	ppm	ppm	ppm	%	%	%	%	RPD	MPR
Antimony *	0	50	26.0	25.4	52%	51%	2.33%	51%	20	00.400
Arsenic	2.07	50	46.9	46.3	90%	88%	1.29%			80-120
Barium	61.2	50	108	107	94%	92%	+	89%	20	80 . 120
Beryllium	0	50	42.8	42.0	86%		0.930%	93%	20	80-120
Cadmium	0	50	46.5		 	84%	1.89%	85%	20	80-120
Chromium	20.5	50		45.8	93%	92%	1.52%	92%	20	80-120
Coablt			80.0	78.7	119%	116%	1.64%	118%	20	80-120
	7.84	50	54.5	53.8	93%	92%	1.29%	93%	20	80-120
Copper Lead	12.1	50	57.7	56.8	91%	89%	1.57%	90%	20	80-120
	43.4	50	97.9	96.5	109%	106%	1.44%	108%	20	80-120
Molybdenum Nickel	0	50	45.3	44.9	91%	90%	0.887%	90%	20	80-120
Selenium *	20.2	50	70.2	69.1	100%	98%	1.58%	99%	20	80-120
Silver	0	50	38.4	37.9	77%	76%	1.31%	76%	20	80-120
ii.	0	50	9.14	8.92	18%	18%	2.44%	18%	20	80-120
Thallium *	0	50	39.4	39.3	79%	79%	0.254%	79%	20	80-120
Vanadium Zinc	31.4	50	76.7	75.6	91%	88%	1.44%	90%	20	80-120
LIIIC	70.4	50	117	115	93%	89%	1.72%	91%	20	80-120

^{*} The MS/MSD recoveries and/or RPD were outside of acceptance limits due to sample matrix effects. See LCS for batch validation.

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2. Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD...... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits...... Statistically determined on an annual basis.

te A, Coiton, CA 92324 (909) 370-4667 FAX (909) 370-1 1014 E. Cooley C 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 [818] 779-1844 FAX (818) 779-2465 W. 12th St., Suite 1, Tempe, AZ 85281 [602] 968-8272 FAX (602) 968-



LCS DATA REPORT

METHOD: METALS Instrument: ICP

Date

Analyzed:

7/14/98

Batch:

HG14ME1S

St	R1	PR	Acceptanc Limits
ppm	ppm	%	

Antimony Selenium **Thallium**

50	51.4	103%	80-120
50	44.8	90%	80-120
50	44.2	88%	80-120

Definition of Terms:

St. Concentration of standard added to blank.

R1..... Standard Result

PR Percent Recovery of R1; (R1 / St) X 100

Acceptance Limits...... Statistically determined on an annual basis.

MEAN

PR

Acceptance

Limits



1014 E. Cooley D 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 2465 W. 12th St., Suite 1, Tempe, AZ 85281

MS/MSD DATA REPORT

EPA METHOD: 8270 Matrix: Soil

MSD

PR1

Date

Analyzed:

7/16/98

Sample:

HG01445

Batch:

HG14SE1S

R1

Sp

MS

Analyte
Phenol *
2-Chlorophenol *
1,4-Dichlorobenzene *
N-Nitroso-di-n-propylamine *
1,2,4-Trichlorobenzene *
4-Chloro-3-methylphenol
Acenaphthene *
2,4-Dinitrotoluene
4-Nitrophenol
Pentachlorophenol
Pyrene

ppb	ppb	ppb	ppb	%	%	%	%	RPD	MPR
0	50	35	23	70%	46%	1 41%	1 500/	·	
0	50	34	19	68%			58%	35	10-112
0				 	38%	57%	53%	50	23-134
<u>-</u> -	50	32	12	64%	24%	91%	44%	27	20-124
0.1	50	34	23	68%	46%	39%	57%	38	41-126
0	50	30	16	60%	32%	61%	46%		
0	50	36	31	72%				38	44-142
0.1					62%	15%	67%	33	22-147
	50	35	28	70%	56%	22%	63%	19	47-145
0	50	39	35	78%	70%	11%	74%	47	
0	50	38	35	76%	70%	8.2%			39-139
0	50	32					73%	50	10-132
			29	64%	58%	9.8%	61%	47	17-109
0.1	50	46	46	92%	92%	0.0%	92%	36	52-115
							لـــــــــــــــــــــــــــــــــــــ		V2 110

PR₂

RPD

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD..... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits..... Statistically determined on an annual basis.

^{*} The MS/MSD recoveries and/or RPD were outside of acceptance limits due to sample matrix effects. See LCS for batch validation.

1014 E. Cooley D: ...e A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1

2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-3



16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1



LCS DATA REPORT

EPA METHOD: 8270

Date:

7/16/98

Batch: HG14SE1S	_			
Analyte	St	R1	PR	Acceptance Limits
	ppb	ppb	%	%
Phenol	50	36	72%	10-112
2-Chlorophenol	50	35	70%	23-134
1,4-Dichlorobenzene	50	28	56%	20-124
N-Nitroso-di-n-propylamine	50	35	70%	41-126
1,2,4-Trichlorobenzene	50	30	60%	44-142
4-Chloro-3-methylphenol	50	39	78%	22-147
Acenaphthene	50	37	74%	47-145
2,4-Dinitrotoluene	50	45	90%	39-139
4-Nitrophenol	50	42	84%	10-132
Pentachlorophenol	50	36	72%	17-109
Pyrene	50	46	92%	52-115

Definition of Terms:

St..... Concentration of standard added to blank.

R1 Standard Result

PR Percent Recovery of R1; (R1 / St) X 100

Del Mar Analytical
1022 FAX (949) 201-1229 1667 FAX (909) 370-1046 1644 FAX (819) 779-1843 277 FAX (802) 998-1339
FAX (819) 505-9699 Project/PO Numb
R Holly and of A
Stade CXXISO6-01/8
Sampler: 6, Left Star Number: 6, Left Star Number: 6, Left Star Number: 6, Left Star Star Star Star Star Star Star Sta
Servatives 12
die i vi
Well B.3
(Abundant)
Cairny Dale
m Enyplad.
G
Refiguished By: Jose Trime: ICheck)
10 Med 17 13/98 1540 48 hours
Sample Integrity: (Check illinguishing samples to Del Mar Análytical, client agrees to pay for the services requested on this dhain of cristofiv form and the sample intact of the contract of

	16726	Page of						Special Instructions	JH EESSE	415/2									Chec	5 days	1 normal	By relinquishing Samples to Del Mar Analytical Client account to the March March Analytical Client account to the March March Analytical Client account to the March Mar	ed on this project. Payment for services is
			þį																Turnaround Time:	T,	U 48 hours	Sample In	l analyses perforn
		Σ	Analysis Required		7	49 19	シン	1			-								いたと		1340	2:8) &2	ind any additiona
	,	CHAIN OF CUSTODY FORM		<i>7</i>	V (6)	FI FI	7.1/ B	7							-				Date /Time	' ·· F	Data (Time:	7-13-	of custody form a
_		CUSTO					d3	ļ											でなる	RI	D by	I M	ted on this dhain
	(HAIN OF		·	8/10	7367		1 due										\Box		Received by:	Received in Lab	12/4	: services reques 0 days.
		Project/DO Number	cor O radilibei.	75 08	Phone Number:	Fax Number: C870 \ 306-730	f Sampling t. Date/Time	11/3/18 15/33 an											22:17	10/10	1 2 2 2	1825	es to pay for the sposed of after 30
~	22 FAX (948) 261-1228 67 FAX (909) 370-1046 H FAX (818) 779-1843 72 FAX (802) 968-1338	FAX (819)		^	E K	Fax N	Container # of Type Cont.	200 B										ate (Time:	413/180	Date /Time: 7 / 13 //9	Date /Time:	1/3/98	nple(s) will be dis
(IDe lar, Llyting	2852 Alton Ave., Irvine, CA 82866 (948) 261-1022 1014 E. Cooley Dr., Suite A, Colton, CA 82324 (808) 370-4867 25 Sherman Wey, Suite C-11, Van Nuya, CA 91406 (818) 779-1844 2465 W 12th St., Suite 1, Tempe, AZ 82281 (802) 968-8272	Chesepeake Dr., Sulte 805, San Diego, CA 92123 (619) 505-9596 nt Name/Address:	70: 5/4d A ASTOC	of the	ect Manager.	Wher. Es holysoc	Sample Sample C Description Matrix	of Word doil	vell 13.3	thundant	Coinny Soule	in Emplay	•					wiehed (B): 0		Mished by:	tuished By:	By relinquishing samples to Del Mar Analy	Athin 30 days from the date of invoice. Sample(s) will be disposed of after 30 days.



RESULTS OF LABORATORY ANALYSIS WELL NO. 2



Suite A, Colton, CA 92324 16525 Sherman Way, ... C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-18 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 (619) 505-9596 FAX (619) 505-96 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-12 (909) 370-4667 FAX (909) 370-10 (602) 968-8272 FAX (602) 968-

				= 1717 (002)	1 968-13
R. C. Slade & Associates	Client Project ID:	RCS		88888888888888888888888888888888888888	20820323555
6442 Coldwater Canyon, Suite 2	14		Sampled:	Jul 24, 1	1998
		Coll Mallata on a	Received:	1	1998
Attention: E. La Pensce	Lab Number	: Soil, Well No. 2 Bottom Sediment	Extracted:	1 (1998
Auchdon. L. La r ensce	Lab Number:	HG03023	Analyzed:		-
×	QC Batch:	HG25091S	Reported:		1998
			rreported.	Jul 29, 1	1998

VOLATILE ORGANICS by GC/MS (EDA 0000)

	VOLATILE OF	RGANICS	by GC/MS (EPA 8260)		
Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
Benzene	2.0	N.D.	Ethylbenzene	2.0	N. D
Bromobenzene	5.0	N.D.	Hexachlorobutadiene	5.0	N.D.
Bromochloromethane	5.0	N.D.	Isopropylbenzene	2.0	N.D.
Bromodichloromethane	2.0	N.D.	p-Isopropyltoluene	2.0	N.D.
Bromoform	5.0	N.D.	Methylene chloride	2.0	N.D.
Bromomethane	5.0	N.D.	Naphthalene		N.D.
n-Butylbenzene	5.0	N.D.	n-Propylbenzene	5.0	N.D.
sec-Butylbenzene	5.0	N.D.	Styrene	2.0	N.D.
tert-Butylbenzene	5.0	N.D.	1,1,1,2-Tetrachloroethane	2.0	N.D.
Carbon tetrachloride	5.0	N.D.	1,1,2,2-Tetrachloroethane	5.0	N.D.
Chlorobenzene	2.0	N.D.	Tetrachloroethene	2.0	N.D.
Chloroethane	5.0	N.D.	Tolueno	2.0	N.D.
Chloroform	2.0	N.D.	Toluene	2.0	N.D.
Chloromethane	5.0	N.D.	1,2,3-Trichlorobenzene	5.0	N.D.
2-Chlorotoluene	5.0	N.D.	1,2,4-Trichlorobenzene	5.0	N.D.
4-Chlorotoluene	5.0	N.D.	1,1,1-Trichloroethane	2.0	N.D.
Dibromochloromethane	2.0	N.D.	1,1,2-Trichloroethane	2.0	N.D.
1,2-Dibromo-3-chloropropane	5.0	N.D.	Trichloroethene	2.0	N.D.
1,2-Dibromoethane	2.0	N.D.	Trichlorofluoromethane	5.0	N.D.
Dibromomethane	2.0	N.D.	1,2,3-Trichloropropane	10	N.D.
1,2-Dichlorobenzene	2.0	N.D. N.D.	1,2,4-Trimethylbenzene	2.0	N.D.
1,3-Dichlorobenzene	2.0	N.D.	1,3,5-Trimethylbenzene	2.0	N.D.
1,4-Dichlorobenzene	2.0	N.D. N.D.	Vinyl chloride	5.0	N.D.
Dichlorodifluoromethane	5.0	N.D. N.D.	o-Xylene	2.0	N.D.
1,1-Dichloroethane	2.0		m,p-Xylenes	2.0 ;	N.D.
1,2-Dichloroethane	2.0	N.D.			
1,1-Dichloroethene	5.0	N.D.			
cis-1,2-Dichloroethene	2.0	N.D.			
trans-1,2-Dichloroethene	2.0	N.D.			
1,2-Dichloropropane		N.D.			
1,3-Dichloropropane	2.0	N.D.			
2,2-Dichloropropane	2.0	N.D.			
1,1-Dichloropropene	2.0	N.D.			
cis-1 3-Dichloropropone	2.0	N.D.			
cis-1,3-Dichloropropene	2.0	N.D.			
trans-1,3-Dichloropropene	2.0	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Project Manager

Surrogate Standard Recoveries (Accept	Limits):
Dibromofluoromethane (80-120)	95%
Toluene-d8 (81-117)	104%
4-Bromofluorobenzene (74-121)	99%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <1 of 7>



ARON Ave., Irvine, CA 92606 1014 E. Cool Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-1 (909) 370-4667 FAX (909) 370-10 (818) 779-1844 FAX (818) 779-18 (619) 505-9596 FAX (619) 505-96 (602) 968-8272 FAX (602) 968-10

Extracted:

Analyzed:

Reported:

R. C. Slade & Associates

6442 Coldwater Canyon, Suite 214 North Hollywood, CA 91606 Attention: E. La Pensce

Method Blank

Jul 25, 1998 Jul 25, 1998 Jul 29, 1998

QC Batch:

HG25091S

VOLATILE ORGANICS by GC/MS (EPA 82	60)
------------------------------------	-----

	VOLATILE OF	RGANICS	by GC/MS (EPA 8260)		
Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
BenzeneBromobenzene	2.0	N.D.	Ethylbenzene	2.0	N.D.
Bromochloromethane	5.0	N.D.	Hexachlorobutadiene	5.0	N.D.
Bromodichloromethane	5.0	N.D.	Isopropylbenzene	2.0	N.D.
Bromoform	2.0	N.D.	p-Isopropyltoluene	2.0	N.D.
Bromomothono	5.0	N.D.	Methylene chloride	20	N.D.
Bromomethane	5.0	N.D.	Naphthalene	5.0	N.D.
n-Butylbenzene	5.0	N.D.	n-Propylbenzene	2.0	N.D.
sec-Butylbenzene	5.0	N.D.	Styrene	2.0	N.D.
tert-Butylbenzene	5.0	N.D.	1,1,1,2-Tetrachloroethane	5.0	N.D.
Carbon tetrachloride	5.0	N.D.	1,1,2,2-Tetrachloroethane	2.0	N.D.
Chlorobenzene	2.0	N.D.	Tetrachloroethene	2.0	N.D.
Chloroethane	5.0	N.D.	Toluene	2.0	N.D.
Chloroform.	2.0	N.D.	1,2,3-Trichlorobenzene	5.0	N.D.
Chloromethane	5.0	N.D.	1,2,4-Trichlorobenzene	5.0	N.D.
2-Chlorotoluene	5.0	N.D.	1,1,1-Trichloroethane	2.0	N.D.
4-Chlorotoluene	5.0	N.D.	1,1,2-Trichloroethane	2.0	N.D. N.D.
Dibromochloromethane	2.0	N.D.	Trichloroethene	2.0	N.D. N.D.
1,2-Dibromo-3-chloropropane	5.0	N.D.	Trichlorofluoromethane	5.0	N.D. N.D.
1,2-Dibromoethane	2.0	N.D.	1,2,3-Trichloropropane	10	N.D.
Dibromomethane	2.0	N.D.	1,2,4-Trimethylbenzene	2.0	
1,2-Dichlorobenzene	2.0	N.D.	1,3,5-Trimethylbenzene	2.0	N.D.
1,3-Dichlorobenzene	2.0	N.D.	Vinyl chloride	5.0	N.D.
1,4-Dichlorobenzene	2.0	N.D.	o-Xylene	2.0	N.D.
Dichlorodifluoromethane	5.0	N.D.	m,p-Xylenes	2.0	N.D.
1,1-Dichloroethane	2.0	N.D.	,p 7 (101100	2.0	N.D.
1,2-Dichloroethane	2.0	N.D.			
1,1-Dichloroethene	5.0	N.D.			
cis-1,2-Dichloroethene	2.0	N.D.			
trans-1,2-Dichloroethene	2.0	N.D.			
1,2-Dichloropropane	2.0	N.D.			
1,3-Dichloropropane	2.0	N.D.			
2,2-Dichloropropane	2.0	N.D.			
1,1-Dichloropropene	2.0	N.D.			
cis-1,3-Dichloropropene	2.0	N.D. N.D.			
trans-1,3-Dichloropropene	2.0	N.D. N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Project Manager

Limits):
102%
103%
101%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <5 of 7>



1014 E. Coo , Suite A, Colton, CA 92324 16525 Sherman Way, Sune C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

1070/ 201-1022 FAX (949) 261-1 (909) 370-4667 FAX (909) 370-, (619) 505-9596 FAX (619) 505-9 (602) 968-8272 FAX (602) 968-1

R. C. Slade & Associates	Client Project ID:	: RCS		.55566555566666555	(002) 968-1
6442 Coldwater Canyon, Suite 2	214	1100	campied.	Jul 24	4, 1998
- · · · · · · · · · · · · · · · · · · ·		: Soil, Well No. 2 Bottom Sediment	Received:	Jul 24	4, 1998
Attention: E. La Pensce	Lab Number:	HG03023	Extracted:	Jul 24	4, 1998
	QC Batch:		Analyzed:	Jul 29	
	QO Daton.	HG24SE1S	Reported:	Jul 29	9, 1998

SEMI-VOLATILE ORGANICS by GC/MS (EPA 3550/8270)

Analyte			by GC/WIS (EPA 3550/82	270)	
Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)	Analyte	Reporting Limit µg/Kg (ppb)	Sample Result µg/Kg (ppb)
AcenaphtheneAcenaphthylene	100 100	N.D.	Dimethyl phthalate	100	N.D.
Aniline	150	N.D.	4,6-Dinitro-2-methylphenol	250	N.D.
Anthracene		N.D.	2,4-Dinitrophenol	250	N.D.
Azobenzene	100	N.D.	2,4-Dinitrotoluene	100	N.D.
Benzidine	150	N.D.	2,6-Dinitrotoluene	100	N.D.
Benzoic Acid	1,000	N.D.	Di-N-octyl phthalate	500	N.D.
Benz(a)anthracene	500	N.D.	Fluoranthene	100	N.D.
Benzo(b)fluoranthene	100	N.D.	Fluorene	100	N.D.
Benzo(k)fluoranthene	200	N.D.	Hexachlorobenzene	100	N.D.
Benzo(g h i)pondono	200	N.D.	Hexachlorobutadiene	100	N.D.
Benzo(g,h,i)perylene	150	N.D.	Hexachlorocyclopentadiene.	500	N.D.
Benzyl alphal	200	N.D.	Hexachloroethane	200	N.D.
Benzyl alcohol	200	N.D.	Indeno(1,2,3-cd)pyrene	200	N.D.
Bis(2-chloroethoxy)methane	· 100	N.D.	Isophorone	100	N.D.
Bis(2-chloroethyl)ether	100	N.D.	2-Methylnaphthalene	100	N.D.
Bis(2-chloroisopropyl)ether	100	N.D.	2-Methylphenol	150	N.D.
Bis(2-ethylhexyl)phthalate	1,000	N.D.	4-Methylphenol	150	N.D.
4-Bromophenyl phenyl ether	150	N.D.	Naphthalene	150	N.D.
Butyl benzyl phthalate4-Chloroaniline	500	N.D.	2-Nitroaniline	200	N.D.
2 Chloropophthologo	100	N.D.	3-Nitroaniline	200	N.D.
2-Chloronaphthalene	100	N.D.	4-Nitroaniline	500	N.D.
4-Chloro-3-methylphenol	100	N.D.	Nitrobenzene	500	N.D.
2-Chlorophenol	250	N.D.	2-Nitrophenol	100	N.D.
4-Chlorophenyl phenyl ether	100	N.D.	4-Nitrophenol	500	N.D.
Chrysene	100	N.D.	N-Nitrosodiphenylamine	200	N.D.
Dibenz(a,h)anthracene	250	N.D.	N-Nitroso-di-N-propylamine.	150	N.D.
Dibenzofuran	100	N.D.	Pentachlorophenol	500	N.D.
Di-N-butyl phthalate	250	N.D.	Phenanthrene	100	N.D.
1,3-Dichlorobenzene	100	N.D.	Phenol	150	N.D. N.D.
1,4-Dichlorobenzene	100	N.D.	Pyrene	150	
1,2-Dichlorobenzene	100	N.D.	1,2,4-Trichlorobenzene	100	N.D.
3,3-Dichlorobenzidine	500	N.D.	2,4,5-Trichlorophenol	150	N.D.
2,4-Dichlorophenol	100	N.D.	2,4,6-Trichlorophenol	150	N.D.
Diethyl phthalate	100	N.D.	, , · · · · · · · · · · · · · · · · · ·	150	N.D.
2,4-Dimethylphenol	250	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Rick DiMaio Project Manager

Surrogate Standard Recoveries (Acce	ept. Limits):					
2-Fluorophenol (25-121) 5						
Phenol-d6 (24-113)	68%					
2,4,6-Tribromophenol (19-122)	79%					
Nitrobenzene-d5 (23-120)	61%					
2-Fluorobiphenyl (30-115)	69%					
Terphenyl-d14 (18-137)	90%					
	2-Fluorophenol (25-121)					

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <2 of 7>



4/100 Ave., Irvine, CA 92506 1014 E. Cook Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (949) 261-1022 FAX (949) 261-1 (909) 370-4667 FAX (909) 370-1 (818) 779-1844 FAX (818) 779-1 (619) 505-9596 FAX (619) 505-9 (602) 968-8272 FAX (602) 968-1

R. C. Slade & Associates

6442 Coldwater Canyon, Suite 214 North Hollywood, CA 91606

Attention: E. La Pensce

Method Blank

QC Batch: HG24SE1S

Extracted: Jul 24, 1998 Analyzed: Jul 25, 1998 Reported: Jul 29, 1998

SEMI-VOLATILE ORGANICS by GC/MS (EPA 3550/8270)

Analyte	Reporting	Sample	o by GC/MS (EPA 3550/82 Analyte	•	
	Limit	Result	Analyte	Reporting	Sample
	µg/Kg	μg/Kg		Limit	Resuit
	(ppb)	(ppb)		μg/Kg	μg/Kg
	(FF-7)	(ppb)		(ppb)	(ppb)
Acenaphthene	100	N.D.	Dimethyl phthalate	100	
Acenaphthylene	100	N.D.	4,6-Dinitro-2-methylphenol	250	N.D.
Aniline	150	N.D.	2,4-Dinitrophenol	250 250	N.D.
Anthracene	100	N.D.	2,4-Dinitrotoluene	100	N.D.
Azobenzene	150	N.D.	2,6-Dinitrotoluene		N.D.
Benzidine	1,000	N.D.	Di-N-octyl phthalate	100	N.D.
Benzoic Acid	500	N.D.	Fluoranthene	500	N.D.
Benz(a)anthracene	100	N.D.	Fluorene	100	N.D.
Benzo(b)fluoranthene	200	N.D.	Hexachlorobenzene	100	N.D.
Benzo(k)fluoranthene	200	N.D.	Hexachlorobutadiene.	100	N.D.
Benzo(g,h,i)perylene	150	N.D.	Hexachlorocyclopentadiene.	100	N.D.
Benzo(a)pyrene	200	N.D.	Hexachloroethane	500	N.D.
Benzyl alcohol	200	N.D.	Indeno(1,2,3-cd)pyrene	200	N.D.
Bis(2-chloroethoxy)methane	100	N.D.	Isophorone	200	N.D.
Bis(2-chloroethyl)ether	100	N.D.	2-Methylnaphthalene	100	N.D.
Bis(2-chloroisopropyl)ether	100	N.D.	2-Methylphenol	100	N.D.
Bis(2-ethylhexyl)phthalate	1,000	N.D.	4-Methylphenol.	150	N.D.
4-Bromophenyl phenyl ether	150	N.D.	Naphthalene	150	N.D.
Butyl benzyl phthalate	500	N.D.	2-Nitroaniline	150	N.D.
4-Chloroaniline	100	N.D.	3-Nitroaniline	200	N.D.
2-Chloronaphthalene	100	N.D.	4-Nitroaniline	200	N.D.
4-Chloro-3-methylphenol	100	N.D.	Nitrobenzene	500	N.D.
2-Chlorophenol	250	N.D.	2-Nitrophenol	500	N.D.
4-Chlorophenyl phenyl ether	100	N.D.	4-Nitrophenol	100	N.D.
Chrysene	100	N.D.	N-Nitrosodiphenylamine	500	N.D.
Dibenz(a,h)anthracene	250	N.D.	N-Nitroso-di-N-propylamine.	200	N.D.
Dibenzofuran	100	N.D.	Pentachlorophenol	150	N.D.
Di-N-butyl phthalate	250	N.D.	Phenanthrene	500	N.D.
1,3-Dichlorobenzene	100	N.D.	Phenol	100	N.D.
1,4-Dichlorobenzene	100	N.D.	Pyrene	150	N.D.
1,2-Dichlorobenzene	100	N.D.	1,2,4-Trichlorobenzene	150	N.D.
3,3-Dichlorobenzidine	500	N.D.	2,4,5-Trichlorophenol	100	N.D.
2,4-Dichlorophenol	100	N.D.	2,4,6-Trichlorophenol	150	N.D.
Diethyl phthalate	100	N.D.	~, ,,o monorophenol	150	N.D.
2,4-Dimethylphenol	250	N.D.			

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Rick DiMaio Project Manager

Surrogate Standard Recoveries (Accep	t. Limits):
2-Fluorophenol (25-121)	58%
Phenol-d6 (24-113)	63%
2,4,6-Tribromophenol (19-122)	63%
Nitrobenzene-d5 (23-120)	58%
2-Fluorobiphenyl (30-115)	64%
Terphenyl-d14 (18-137)	90%

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <6 of 7>



Alton Ave., Irvine, CA 92606 , Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-1 (909) 370-4667 FAX (909) 370-1 (818) 779-1844 FAX (818) 779-18 (619) 505-9596 FAX (619) 505-96 (602) 968-8272 FAX (602) 968-10

R. C. Slade & Associates

6442 Coldwater Canyon, Suite 214

North Hollywood, CA 91606 Attention: E. La Pensce

Client Project ID: RCS

Sample Descript: Soil, Well No. 2 Bottom Sediment Lab Number: HG03023

Sampled: Received: Extracted:

Jul 24, 1998 Jul 24, 1998 Jul 27-29, 1998

Analyzed: Jul 28-29, 1998 Reported: Jul 29, 1998

CALIFORNIA CODE OF REGULATIONS, TITLE 22 METALS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/Kg (ppm)		TTLC Sample Result mg/Kg (ppm)
Antimony	6010	15	500	10		N.D.
Arsenic	6010	5.0	500	2.0	•••••	8.9
Barium	6010	100	10000	1.0	***************************************	15
Beryllium	6010	0.75	75	0.50	***************************************	N.D.
Cadmium	6010	1.0	100	0.50	*******	1.5
Chromium, total	6010	5.0	2500	1.0	***************************************	11
Cobalt	6010	80	8000	1.0	***************************************	4.2
Copper	6010	25	2500	1.0	*******	89
Lead	6010	5.0	1000	2.0		9.8
Mercury	7471	0.20	20	0.020	***************************************	N.D.
Molybdenum	6010	350	3500	2.0	***************************************	3.2
Nickel	6010	20	2000	1.0		64
Selenium	6010	1.0	100	2.0		N.D.
Silver	6010	5.0	500	1.0	******************	N.D.
Thallium	6010	7.0	700	10		N.D.
Vanadium	6010	24	2400	1.0		4.0
Zinc	6010	250	5000	5.0	•••••••	33
				-		55

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Project Manager

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <3 of 7>

1014 E. Cook Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (949) 261-1022 FAX (949) 261-1 (909) 370-4667 FAX (909) 370-1 (818) 779-1844 FAX (818) 779-1 (619) 505-9596 FAX (619) 505-9 (602) 968-8272 FAX (602) 968-1

Extracted: Jul 27-29, 1998 Analyzed: Jul 28-29, 1998 Reported: Jul 29, 1998

R. C. Slade & Associates 6442 Coldwater Canyon, Suite 214 North Hollywood, CA 91606 Attention: E. La Pensce

Method Blank

CALIFORNIA CODE OF REGULATIONS, TITLE 22 METALS

Analyte	EPA Method	STLC Max. Limit mg/L (ppm)	TTLC Max. Limit mg/Kg (ppm)	Reporting Limit mg/Kg (ppm)		TTLC Sample Result mg/Kg (ppm)
Antimony	6010	15	500	10		N.D.
Arsenic	6010	5.0	500	2.0	***************************************	N.D.
Barium	6010	100	10000	1.0	***************************************	N.D.
Beryllium	6010	0.75	75	0.50	••••••	N.D.
Cadmium	6010	1.0	100	0.50	***************************************	N.D.
Chromium, total	6010	5.0	2500	1.0		N.D.
Cobalt	6010	80	8000	1.0		N.D.
Copper	6010	25	2500	1.0	***************************************	N.D.
Lead	6010	5.0	1000	2.0		N.D.
Mercury	7471	0.20	20	0.020	***************************************	N.D.
Molybdenum	6010	350	3500	2.0	***************************************	N.D.
Nickel	6010	20	2000	1.0		N.D.
Selenium	6010	1.0	100	2.0		N.D.
Silver	6010	5.0	500	4.0	•••••••••••••••••••••••••••••••••••••••	N.D.
Thallium	6010	7.0	700	40	•••••••••••••••••••••••••••••••••••••••	
Vanadium	6010	24	2400	1.0		N.D.
Zinc	6010	250	5000	5 0	••••••	N.D.
			-	0.0		N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Rick DiMaio Project Manager

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <7 of 7>



Attention: E. La Pensce

1014 E. Cook Suite A, Colton, CA 92324 16525 Sherman Way, Sans 8-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123

(949) 261-1022 FAX (949) 261-122 (909) 370-4667 FAX (909) 370-104 (818) 779-1844 FAX (818) 779-184 (619) 505-9596 FAX (619) 505-968 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-133

R. C. Slade & Associates Client Project ID: RCS 6442 Coldwater Canyon, Ste. 214 North Hollywood, CA 91606

Sample Descript: Soil First Sample #: HG03832

Sampled: Jul 24, 1998 Received: Jul 24, 1998 Extracted: Jul 31, 1998 Analyzed: Jul 31, 1998 Reported: Aug 4, 1998

CHROMIUM VI (EPA 7196)

Laboratory Number	Sample Description	Reporting Limit mg/Kg (ppm)	Sample Result mg/Kg (ppm)
HG03832	Well No. 2 Bottom Sediment	0.50	N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03832,RCS <1 of 2>



Del Mar Analyucal

North Hollywood, CA 91606

Attention: E. La Pensce

1014 E. Cook Suite A, Colton, CA 92324 16525 Sherman Way, Sund C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-122 (909) 370-4667 FAX (909) 370-104 (818) 779-1844 FAX (818) 779-184 (619) 505-9596 FAX (619) 505-968 (602) 968-8272 FAX (602) 968-130

Extracted: Analyzed: Reported:

Jul 31, 1998 Jul 31, 1998 Aug 4, 1998

6442 Coldwater Canyon, Ste. 214

Method Blank

CHROMIUM VI (EPA 7196)

Laboratory Sample Description **Reporting Limit** Result mg/Kg mg/Kg (ppm) (ppm) Method Blank 0.50 N.D.

Analytes reported as N.D. were not present at or above the reporting limit.

DEL MAR ANALYTICAL (ELAP #1197)

Patty Mata Project Manager

> Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03832.RCS <2 of 2>

III Ave., Irvine. CA 92606

1014 E. Cooley L

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1

(714) 261-1022 FAX (714) 261-1 uite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX [602] 968-3

MS/MSD DATA REPORT

EPA METHOD: 7196 Matrix: Soil

Date

Analyzed:

7/31/98

Sample:

HG03832

Batch:

HG31C61S

Analyte	R1 Sp M		MS	MS MSD	PR1 PR2		RPD	MEAN PR	Acceptance Limits	
	ppm	ppm	ppm	ppm	%	%	%	%	RPD	MPR
Chromium VI	0	3.33	0	0	0%	0%	0%	0%	20	80-120

^{*} The MS/MSD recoveries and/or RPD were outside of acceptance limits due to sample matrix effects. See LCS for batch validation.

Definition of Terms:

R1	Result of Sample Analysis
	Spike Concentration Added to Sample
MS	
	Matrix Spike Duplicate Result
	Percent Recovery of MS; ((MS-R1) / SP) X 100
PR2	Percent Recovery of MSD; ((MSD-R1) / SP) X 100
RPD	Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100
Acceptance Limits	Statistically determined on an annual basis

on Ave., Irvine, CA 92606 (714) 261-1022 FAX (714) 261-1 1014 E. Cooley L

lite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-10 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-3

LCS DATA REPORT

EPA METHOD: 7196

Date

Analyzed:

7/31/98

Batch:

HG31C61S

Analyte	St	R1	PR	Acceptance Limits	
	ppm	ppm	%	%	
Chromium VI	3.0	2.8	93%	80-120	

Definition of Terms:

St..... Concentration of standard added to blank. R1...... Standard Result PR Percent Recovery of R1; (R1 / St) X 100

Acceptance Limits.... Statistically determined on an annual basis.

16525 Sherman Way, Suite C Van Nuys, CA 91406 (818) 779-1844 FAX (909) 370-2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-

ADDITIONAL ANALYSIS REQUEST FORM

	,				A STATE OF THE PARTY OF THE PAR
Today's Date: 7/3	0/98 Dell	Mar Analytica	l Project Manager:	RD For	PM
Request via: X tel	lephone chain	of custody form	fax transmission	E-mail o	ther
Client: R.C. SLA	HDE & ASSOC	Contact:	GAL		
Project: RCS					
Date Sampled:	7/24/98	Date R	Received: 7/20	1/98	
Status: in progress					
SAMPLE NUMBER	SAMPL DESCRIPT	.E	ANALYSIS REQUESTED	SPECIA	L
H603023 1	DEL No.2 BE	MM SÉDIMEN	7 CHROME	6t	
		•			
					·
	4				
TURNAROUN	D STATUS:	Same Day		3days	
	5days _	Standard	No Rush Charge		
			g:\dmai\misc\for	rms\add-req.doc	



1014 E. Cool Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 92103 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281 (949) 261-1022 FAX (949) 261-12 (909) 370-4667 FAX (909) 370-10 (818) 779-1844 FAX (818) 779-18 (619) 505-9596 FAX (619) 505-96 (602) 968-8272 FAX (602) 968-13

Jul 29, 1998

R. C. Slade & Associates

Client Project ID: RCS

6442 Coldwater Canyon, Suite 214 North Hollywood, CA 91606 S

Attention: E. La Pensce

Sample Descript: Soil First Sample #: HG03023 Sampled: Jul 24, 1998 Received: Jul 24, 1998 Extracted: Jul 24, 1998 Analyzed: Jul 24, 1998

Reported:

pH (EPA 9045)

		1 (
Laboratory Number	Sample Description	Reporting Limit pH units	Sample Result pH units		
HG03023	Well No. 2 Bottom Sediment	N.A.	9.1		

DEL MAR ANALYTICAL (ELAP #1197)

Rick DiMaio Project Manager

Results pertain only to samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

HG03023.RCS <4 of 7>

1014 E. Coole Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

MEAN

PR

(909) 370-4667 FAX (909) 370-10 (818) 779-1844 FAX (818) 779-18 (619) 505-9596 FAX (619) 505-96 (602) 968-8272 FAX (602) 968-13

Acceptance

Limits

MS/MSD DATA REPORT

EPA METHOD: 8260 Matrix: Soil

Date

Analyzed:

7/25/98

Sample:

HG03109

Batch:

HG25091S

R1

Sp

MS

MSD

PR₁

PR2

RPD

Analyte
- militation
Vinyl Chloride
1,1-Dichloroethene
MTBE
1,1-Dichlororethane
Chloroform
1,2-Dichlororethane
Benzene
Trichloroethene
Toluene
Tetrachloroethene
Chlorobenzene
Ethylbenzene
m,p-Xylenes

ppb	ppb	ppb	ppb	%	%	%	%	RPD	MPR
0	25	31	28	124%	112%	10%	118%	30	T 30 400
0	25	28	28	112%	112%	0.0%	112%	1)	30-160
0.6	25	20	26	78%	102%	 	 	40	45-165
0	25	27			 	26%	90%	40	55-155
 		 	27	108%	108%	0.0%	108%	20	55-150
0.4	25	27	28	106%	110%	3.6%	108%	20	65-140
0	25	23	25	92%	100%	8.3%	96%	30	55-145
0	25	26	26	104%	104%	0.0%	104%	25	60-140
0	25	28	27	112%	108%	3.6%	110%	30	
0	25	27	26	108%	104%	3.8%	106%		60-145
0	25	29	28	116%				20	65-140
0	25				112%	3.5%	114%	50	10-200
<u> </u>	+	26	26	104%	104%	0.0%	104%	20	70-135
0	25	27	26	108%	104%	3.8%	106%	20	70-140
0	50	53	51	106%	102%	3.8%	104%		
0	25	27	26	108%				20	40-160
<u> </u>				100%	104%	3.8%	106%	20	65-150

Definition of Terms:

o-Xylene

R1..... Result of Sample Analysis

Sp. Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1. Percent Recovery of MS; ((MS-R1) / SP) X 100

PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD..... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits..... Statistically determined on an annual basis.

1014 E. Coole Suite A, Colton, CA 92324
16525 Sherman Way, Suite C-11, Van Nuys, CA 91406
9484 Chesapeake Dr., Suite 805, San Diego, CA 92123
2465 W. 12th St., Suite 1, Tempe, AZ 85281

(949) 261-1022 FAX (949) 261-12 (909) 370-4667 FAX (909) 370-10 (818) 779-1844 FAX (818) 779-194 (619) 505-9596 FAX (619) 505-964 (602) 968-8272 FAX (602) 968-13

MS/MSD DATA REPORT

EPA METHOD: 7471 Matrix: Soil

Date

Analyzed:

7/29/98

Sample:

HG03380

Batch:

HG29HG1S

Analyte	R1	Sp	MS	MSD	PR1	PR2	RPD	MEAN PR		otance nits
	ppm	ppm	ppm	ppm	%	%	%	%	RPD	MPR
Mercury	0	0.80	0.748	0.746	94%	93%	0.3%	93%	20	80-120

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100

PR2..... Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD...... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits...... Statistically determined on an annual basis.

Del Mar Analytical

1014 E. Cook Suite A, Colton, CA 92324 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

MEAN

PR

(949) 261-1022 FAX (949) 261-12 (909) 370-4667 FAX (909) 370-10. (818) 779-1844 FAX (818) 779-184 (619) 505-9596 FAX (619) 505-968 (602) 968-8272 FAX (602) 968-133

Acceptance

Limits

MS/MSD DATA REPORT

EPA METHOD: 8270 Matrix: Soil

MSD

PR1

Date

Analyzed:

7/25/98

Sample:

HG02446

Batch:

HG24SE1S

R1

Sp

Analyte
Phenol *
2-Chiorophenoi *
1,4-Dichlorobenzene *
N-Nitroso-di-n-propylamine *
1,2,4-Trichlorobenzene *
4-Chloro-3-methylphenol *
Acenaphthene *
2,4-Dinitrotoluene *
4-Nitrophenol *
Pentachlorophenol *
Pyrene *

ppb	ppb	ppb	ppb	%	%		%	RPD	MPR
0	50	0	2	0%	4%	200%	2%	35	10-112
0	50	2	1	4%	2%	67%	3%	50	23-134
0	50	1	1	2%	2%	0%	2%	27	20-124
0.4	50	2	1	3%	1%	67%	2%	38	41-126
0	50	1	1	2%	2%	0%	2%	38	44-142
0	50	1	1	2%	2%	0%	2%	33	22-147
0.1	50	1.	1	2%	2%	0%	2%	19	47-145
0	50	1	1	2%	2%	0%	2%	47	39-139
0.2	50	0	0	0%	0%	NA	0%	50	10-132
0	50	0	0	0%	0%	NA NA	0%	47	
0.1	50	2	2	4%	4%	0.0%	4%		17-109
L	<u> </u>			. 70	L 7/0	0.076	470	36	52-115

PR₂

RPD

Definition of Terms:

R1..... Result of Sample Analysis

Sp. Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

RPD...... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits..... Statistically determined on an annual basis.

^{*} The MS/MSD recoveries and/or RPD were outside of acceptance limits due to sample matrix effects. See LCS for batch validation.

1014 E. Cook Suite A, Colton, CA 92304 16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 2465 W. 12th St., Suite 1, Tempe, AZ 85281

Acceptance

Limits

(949) 261-1022 FAX (949) 261-12 (909) 370-4667 FAX (909) 370-10 (818) 779-1844 FAX (818) 779-18 (619) 505-9596 FAX (619) 505-96 (602) 968-8272 FAX (602) 968-13

LCS DATA REPORT

EPA METHOD: 8270

St

Date:

7/25/98

Batch:

Pyrene

HG24SE1S

Analyte
Phenol
2-Chlorophenol
1,4-Dichlorobenzene
N-Nitroso-di-n-propylamine
1,2,4-Trichlorobenzene
4-Chloro-3-methylphenol
Acenaphthene
2,4-Dinitrotoluene
4-Nitrophenol
Pentachlorophenol

ppb	ppb	%	%
50	34	68%	10-112
50	35	70%	23-134
50	30	60%	20-124
50	40	80%	41-126
50	32	64%	44-142
50	39	78%	22-147
50	38	76%	47-145
50	39	78%	39-139
50	39	78%	10-132
50	33	66%	17-109
50	49	98%	52-115

PR

R1

Definition of Terms:

St..... Concentration of standard added to blank.

R1..... Standard Result

PR Percent Recovery of R1; (R1 / St) X 100

n Ave., trvine, CA 92606 [714] 261-1022 FAX (714) 261-2852

2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-

1014 E. Cooley D. Jite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-

MS/MSD DATA REPORT

METHOD: METALS Instrument: ICP

Matrix: Soil

Date

Analyzed:

7/28/98

Sample:

HG03229

Batch:

HG27ME1S

Analyte	R1	Sp	MS	MSD	PR1	PR2	RPD	MEAN PR	Acceptance Limits	
M///	ppm	ppm	ppm	ppm	 %	%	%	%	RPD	MPR
Antimony	3.23	50	45.0	45.7	84%	85%	1.5%	84%	20	80-120
Arsenic	2.82	50	46.6	46.3	88%	87%	0.65%	87%	20	80-120
Barium	160	50	218	222	116%	124%	1.8%	120%	20	80-120
Beryllium	0	50	45.0	45.4	90%	91%	0.88%	90%	20	80-120
Cadmium	1.0	50	47.8	48.5	94%	95%	1.5%	94%	20	80-120
Chromium	22.0	50	80.0	81.2	116%	118%	1.5%	117%	20	80-120
Cobalt	9.13	50	59.2	60.1	100%	102%	1.5%	101%	20	80-120
Copper	16.0	50	67.9	69.4	104%	107%	2.2%	105%	20	80-120
Lead	5.44	50	51.6	52.1	92%	93%	0.96%	93%	20	80-120
Molybdenum	1.58	50	46.6	47.2	90%	91%	1.3%	91%	20	80-120
Nickel	34.0	50	86.5	87.6	105%	107%	1.3%	106%	20	80-120
Selenium *	0	50	36.7	37.8	73%	76%	3.0%	75%	20	80-120
Silver	0	10	8.97	9.23	90%	92%	2.9%	91%	20	80-120
Thallium *	0	50	38.6	39.1	77%	78%	1.3%	78%	20	80-120
Vanadium *	42.0	50	110	112	136%	140%	1.8%	138%	20	80-120
Zinc	52.0	50	108	110	113%	116%	1.6%	114%	20	80-120

Definition of Terms:

R1..... Result of Sample Analysis

Sp..... Spike Concentration Added to Sample

MS..... Matrix Spike Result

MSD..... Matrix Spike Duplicate Result

PR1..... Percent Recovery of MS; ((MS-R1) / SP) X 100 PR2. Percent Recovery of MSD; ((MSD-R1) / SP) X 100

RPD..... Relative Percent Difference; ((MS-MSD)/(MS+MSD)/2) X 100

Acceptance Limits..... Statistically determined on an annual basis.

16525 Sherman Way, Suite C-11, Van Nuys, CA 91406 [818] 779-1844 FAX (818) 779-1



2465 W. 12th St., Suite 1, Tempe, AZ 85281 (602) 968-8272 FAX (602) 968-3

LCS DATA REPORT

METHOD: METALS Instrument: ICP

Date

Analyzed:

7/28/98

Batch:

HG27ME1S

Acceptance St R1 PR Limits ppm % ppm %

Selenium **Thallium** Vanadium

50	47.9	96%	80-120
50	45.7	91%	80-120
50	46.2	92%	80-120

Definition of Terms:

St. Concentration of standard added to blank.

R1..... Standard Result

PR Percent Recovery of R1; (R1 / St) X 100

Acceptance Limits.... Statistically determined on an annual basis.

due within 30 days from the date of invoice. Sample(s) will be disnosed of after 30 dave



APPENDIX 5 CEMENT DELIVERY TICKETS

POI	CPEN 7 DAYS BOX 33140 RIVERSIDE CA 925 19	CONTROL 413446
#1 ANTASIDE - 8830 VAN BUREN BLYD. #6 HEMET/SAN JACINTO - 1975 S #2 NOFEÑO VALLEY ; 12860 DAY STREET #7 BEALMONT - 452 FIFTH PLACE #3 RECLANDS - 8555 ALABAMA #8 SUN CITY - 27050 WATSON RO #4 FONTANA - 13792 SLOVER #9 ARROWHEAD - 29750 HWY 18 #5 POMONA - 2470 POMONA BLYD. #10 SANTA FE SPRINGS - 12311 GRE	AN AN HEM SILES THOO SANTA ANA CANYON RD. AD 913 [ANAIDALE 1383] LIVE OAK LANE 914 PASADENAL 1420 N LINCOLN AVENUE	#18 AWAHEM - 201 E. COMMERCIAL #17 SANTA ANA - 310 N. TOWNSEND #18 LAKE FOREST - 29531 TOWN CENTRE #19 ADELANTO - 12203 MOLET IND #20 SAN CLEMENTE - 116 RINCON CT. #21 IRVINE - 16081 CONSTRUCTION CIR. WEST
PLANT DATE CUSTOMER NO. SOLD TO		MAP PAGE TICKET NO.
10 08/13/98 53680 BEY TX CD DELIVERY ADDRESS & INSTRUCTIONS 190TH/NORMANDIE BOEING PLANT Job Phone :	이 문화 등이 보고 다른 보면 모든 다른데 생물이 하는 물 때 가지 않는 것이 하는 점 되었다. 그 때 가까지 않다.	764A2 41344 CUSTOMER PO. / JOB OR LOT # 95-8007 05-8007 -0903LAST TKS
CPU NO. METER READING TIME TYPED. 147 1800. 30 12:12	TRUCK LIC NO. 5893070	
LOAD NO. SLUMP TRUCK DRIVER 1 6.00 542 1076	MACLEAN NEIL SLURRY	
TO JOB 1239 PRUM Job-site Cylinder Test	☐ Yes TIME ON JOB	MIN CHECK#
ON JOB 1313 Water added on job at Customer's request:	DIANUBI	MIN. CHECK AMOUNT STEELS
START POUR 1209 gals to f	73 Ld	MIN DASH WARMOUNT TO BY PLANT MGR SIG
CEAVE JOB ARRIVE B AND THE ADDITION OF THE ADD	ics La. Ster 4 MIN 4 min per yd. 1 Oncrete will 4 ddison Lucio	ree unloading time allowed. ading time charged at
reduce its strength. Any water customer's own risk	edded is at Current hourly	ruck fate
in event of default in payment of this ticket and it is necessary for seller sto retain the services of an energy for seller sto retain the services of an energy for the payer serves to pay seller all costs and expenses incurred by reason thereof, including a reasonable attorney of set plus 1/2. This release is interest per month. **The payment of this picket and it is necessary to receive the payment of	ertson's (Material Dealer) delivering fais purchased material to a pic- rees to indemnity and tool barmless said Material Dealer, their hor or if them, to all real and personal property at the location indicated loyees upon or about such property. to, and does power all inovernents of all vehicles of said Material D curb line to enter upon the property described hereon until they retu-	ace designated by the undersigned, the undersigned ints lemployees and drivers from all liability or claims before as a result of the movement of said Materia lealer, at the location indicated hereon, from the time of to buch burb line, regardless of the number and/o
LOAD CUMULATIVE DRIVERED PRODUCT QUANTITY QUANTITY COOPE	MIX AND COMMODITY UNI	TOF UNIT AMOUNT
3.50 3.50 3.50 RC940P1	3 10.09K SLURRY CY	
Javel 10. 3		
LOAD WEIGHT SSD: Casing Cement	DEL. CHARGE WEIGHMASTER CERTIFICATE THIS IS TO CERTIFY that the following described commodity is	A CONTRACTOR OF THE CONTRACTOR
LOAD WEIGHT SSD: Casing Cement 8.1.1	measured, or counted by a weighmaster whose signature is on the who is a recognized authority of accuracy, as prescribed by (commencing with Section 12700) or Division 5 of the California Professions Code, administered by the Division of Measurement Standard California Department of Food and Agriculture.	iis certricate, y Chapter, 7 Business and IPREVIOUS
	ROBERTSONS WEIGHMASTER Dave Galias	SÜB TOTAL
\bigvee_{n}	BY DEPUTY	— STAND BY CHARGE
Whit most	MAX ALLOWABLE WATER	TOTAL
RECEIVED BY	DELIVERY TICKET	

THIS IS TO CERTIFY that the following described commodity as weighed, measured, or counted by a weighmaster, flose signature is on this certificate, who is a recognized authority of accuracy, as prescribed by Chapter 7 (commencing with Section 12700) of Division 5 of the California usiness and Professions Code, administered by the ivision of Measurement Standards of the California epartment of Food and Agriculture.



STANDARD CONCRETE PRODUCTS, INC.

Serving Southern California since 1949

TO VERY TICKET NO.


DATE


EASURED AT: 49-2521092

PALOS VERDES (310)-517-8225

	SOLD TO	9	/ SCHED A	RRIVAL 14:00	and the second of the second o					
T · .	CUSTOMER NO.	354 BEYLIK	DRILLING, II		ing panggan pangganggan Panggan panggan panggan	Y	D ³ / M ³ THIS TIC	KET OO	Januari I	OTAL YD3 / M3
	JOB ADDRESS	190TH TORRAN	& NORMANDIE CE	Bright and San San San San	nerger (1965) (1966) Adulti (1966) (1966) (1966) Tillian (1966)	N	ios#	<u>Partie Steleti</u> Bartistanger Lijimon anas	The first of the second	USTOMER JOB # 05-7981
J						P.	0.# 05-79 :	81	#5126 (44)	
	CROSS STREET/	SPECIAL INSTRUCTION	्रिक्तिक स्थापना क्षेत्रक कि है स्थापना भित्तिक कि कि कि कि स्थापना स्थापना क्षेत्रक क्षेत्रक क्षेत्रक क्षेत्रक क्षेत्रक क्षेत्रक क्षेत्रक क्षेत्रक क् अस्तिक स्थापना	en e	teritorio de la companio de la comp La companio de la co	61	IAP PAGE 197 0	53	P	UC ZONE 1976
	The second secon	721		is armon finance tead to	TOP SIZE AGGREGATE SLI	UMP/PENET	TRATION CEME	ENT TYPE	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
	2404.3	SACK EQ SA	ND SLURRY (6.		en er	andre e	THE STATE OF THE S	STATE OF STATE	o obstable	
			· 在一个中心。 全人的图像是一个中心。可以是			,, , , , , , , , , , , , , , , , , , ,	and Web Tools	Friday Par	A Variati Mism. To	
		BRUCE D.	The state of the s	STORESTER THE STORESTER STORES	LOAD#				A Community A Community A Community	
	PRIVATE WEIGHA	AASTER /	A PORT OF A PORT OF THE PARTY O	e <mark>ole,</mark> nelso belore snipres elle dellay o distressors	Miller of Depthy Enterly Right yill been be ed give	CUBIC	YARDS/ METERS	PRICE	7 19 10 1	EXTENSION
à	LEAVE PLANT		ARRIVE JOB	1. 4. 4. 9 mg	Cntr-Strt	ADMIX	OUS BALANCE	AN ALPHANING AS AN ALPHANIA 3. Facility (Special	see tradicial	
	START UNLOAD	147	FINISH UNLOAD	1002		SLC	1200	416 Origin	Strate 1	
N .	LEAVE JOB		ARRIVE PLANT		Cntr-UnLd	SALES	and the second of	Applet 2	grandinasis grandinasis	
		www.allegaria	int House I have been stronged as with the been published to	<u>lear med enedises eabla</u> Kilonia vijesik syanomati	Banda series de la succe de los socialmentes de la visión	OVERT	ITAL IME		Estata Name	OVERTIME CH.
<u>.</u>	MIN	UTES PER CUBIC YARD/CUBIC	C METER FREE UNLOADING TIME AL	LOWED. ADDITIONAL UNLOAD TIN	IE CHARGED AT CURRENT RATE	11/25 %	ik (17) le (*) Kropester	f gan th Line	(2 19 Sec.)	MIN.
	136	WATER ADDED AT JOB SITI		PLANT WATER ALLOW JOBWATER MAX ALLOWABLE WATER	M³ Willin 1 "/25.4m	crease slun	ice the 28 day	TOTAL		
	1032	MATERIALS ACROSS	NCRETE DOES NOT C ED FROM ANY RESPONSIBILI SIDEWALK AND CURB. STAND	LY UE ADDITION OF COLORS	OR ADMIXTURES AND FO	RDAMAG	ES WHICH M	OLOREI AY BE INCU	D CONCI RRED IN DE	RETE MIX. LIVERING
· · · · · · · · · · · · · · · · · · ·	N -1	RECEIVED BY:	GOMMAY	/ OTHER	REMARKS			1991 1991 1992 1992 1993 1994	ins all Lawrence Lawrence	
*1		A CBR COMPANY		INSPECT	TORS COPY					

Well No. 3 caring coment. E.L.L.





MAX ALLOWABLE WATER

DELIVERY TICKET

CHARGE

TOTAL

